1989

MY LETTER MY ETC

() '

Interritions III.

<u>Bob Casale</u>

October 10, 1989

City of Freeport Administration 128 East 4th Street Freeport, Texas 77541

Dear Sirs:

We are bringing a continuous problem to your attention which we have complained about for several years.

RECEIVED

OCT 18 1989

Region 7

Texas Air Control Board

The subject matter is the operation of Fish Engineering and Hercules Off-Shore Drilling Company.

We have enclosed a letter dated October 5, 1989 to that Company.

In general our complaints have been the exposure to dangerous chemicals, exposure to sand-blasting materials, and the loud abusive noises.

Each time we have complainted to the city manager, the health department, members of city council, also to Mayor Alan Faulk and past Mayor Mark Vanderveer we have received no response to curtail the operation or safe-guard the health and safety of the adjacent residences.

As the October 5, 1989 letter indicates the present Company is engaged in the barge cleaning process. There is one case in particular that the residents were heavily exposed to benezene gas. I called the city manager and asked if he would send the health officer to investigate the matter. Two hours had pasted and no-one appeared from the city to investigate. I then called back and the operator told me everyone had gone to lunch; apparently lunch is more important to the city than to go out and investigate persons who are being exposed to dangerour gases. Finally about three days later a city health officer and a member of the Texas Air Control Soard came to the scene. At that point we had a lengthy discussion as to the problems we are having with these companies. At that time we again showed pictures of the leaves of the trees that had died due to chemical releases.

Dangerous chemicals are extracted from the barges and vents are being opened exposing residents to gas releases. There has been several incidents where the barges are brought in at night and the hatches are being opened durning the time that the residents are sleeping; making us un-aware of the danger until morning.

The continuous sand-blasting which sometimes starts a 7:30 a.m. till dark has caused us many problems. We are unable to open our windows; our automobilies have been damaged and covered with the over-spray. Our downstairs patio is also always filled with

particles of the sand-blasting. When we attempt to breath outdoors our lungs, throat, eyes and nose are filled with the particles. As we write this letter at 6:00 p.m. the sand-blasting is taking place. A cloud of dust can be visually seened. We are unable to open windows, the high pressure screeching sound from the sand-blasting can be heard from the furtherest room in our home.

About a month ago I requested that Mayor Alan Faulk meet me at my house to investigate this matter. When he visited, I showed him the close proximity of this business to our residences. He agreed that we do have a problem. I then showed him our downstairs patio; and asked him to rub his hand over the thick debris on a table top which was filled with over-spray from the business. I then asked him to investigate this matter further; as to what remedies can be taken to curtail and cease the annoying and dangerous process.

Three days past without word from Mayor Alan Faulk. I called him; to ask if he had finish his investigation. He responded that he had talked to the city manager and city attorney and they said nothing could be done by the city because the city re-zoned the land to conduct that type of business. I told him, in the future, I wish to add on to my house, he said "quote" that you "Bob Casale" should straighten out that problem "being Hercules" before you add on to your house. He also told me that I should call Marvin Zindler from T.V. channel 13 in Houston; to have him investigate; maybe he could do something.

If I ever experienced devalication of duty, from a governmental official this is a prime example.

We have also mentioned about the loud abusive noise. Many times durning the operational phase of this business they bang on barges and the sounds are heard through-out the subdivision.

The recorded facts relate that the business location has caused these problems for many years.

On April 17,1989 the city of freeport held a city council and planning commission public hearing to re-zone several parcels of land in and around the Bridge Harbor Subdivision, including the business in question. After hearing from approximately thirty persons opposing this zone change, the city ignored the compleints and went on to re-zone the land from light manufacturing to water-front heavy. This action to us was pure irresponsiable and deliberate unconcern for the health and safety for near-by residence; knowing the dangerous consequence and nuisance that this change made.

Several times officals with the Texas Air Control Board told me that I should call the city of Freeport so that they could make an immediate investigation. I was told by city officals that the city did not have a qualified person to investigate.

As of this date we are requesting that the city of Freeport contact the County Health Department for assistance. I have had several discussions with County Judge John Damon and he stated that their office would assist if requested by the City of Freeport.

About 12:45 n.m. October 11, 1989 I met Robby Blair on the corner of . He told me that he was investigating that mornings complaint. I showed him the over-spray blowing over the city street and pointed out the loud blasting noise. I also told him that he should talk to the shrimper Danny Marches working about two hundred feet from us, and adjacent to the barge being sand-blasted. He refused to go. I then went to Danny Marches and told him what had happen.

In summary we wish to inform, that city officals, have a moral and legal responsibility to the people and have a duty to safe-guard the safety and welfare of the citizens.

As of this date we find no documentation where the city of Freeport has made any attempt to safe-guard and protect the citizens in this case.

We here-by notify the city officals, who were resposiable for the damaging zone changes and allowing the problems to occur past and present; that we are holding them resposiable for damanges to health and property in this case.

In trust, we hope the city officals who are in-powered to act, and according to law; to safe-guard the citizens in this case, and act with deligence.

Thank You. Pasale
Tella Casale
Bob and Stella Casale

CC:

Mayor Alan Faulk Councilman: Jim Phillips Milan Miller John Stanford Horace Owings Brazoria County Health Department

Texas Air Control Board
EPA
Jim Mattox - Texas Attorney General
J.E. "Buster" Brown - State Senator
John Willy - State Representative
Tom Delay - U.S. Representative



Region 7 Texas Air Control Board

The second secon

January 25, 1989

Texas Air Control Board 6330 Hwy 290 East Austin, Texas 78723

Attention: Bill Stewart, P.E.

Executive Director

Subject:

Permit Exemption X-3561 Barge Cleaning Facility Freeport, Brazoria County

Dear Sir:

Please be advised that effective January 20, 1989, Fish Engineering & Construction, Inc. sold the Fish Marine Yard to Hercules Offshore Drilling Company, 11381 Meadowglen Lane, Houston, Texas 77082. The mailing address, telephone number and type of business will remain the same.

We hereby request transfer of this registration to Hercules Offshore Drilling Company. Please adjust your records accordingly, and if additional information is desired, please contact the undersigned at the address indicated above.

Sincerely,

Tom Randolph

Marine Manager

TR/se

cc: Mr. Hunt

5555 West Loop, Suite 300 Bellaire, Texas 77401

... Kouch Gla



FISH ENGINEERING & CONSTRUCTION, INC.

O. Box 22535 • Houston, Texas 77227







CERTIFIED

P 598 180 683

MAIL

Mr. Hunt 5555 West Loop, Suite 300 Bellaire, Texas 77401



JAN 26 1989

Region 7
Texas Air Control Board



Strength through experience, equipment, know-how 11381 Meadowglen Lane @ Houston, Texas 77082 (713) 497-7934

January 25, 1989

RECEIVED JAN 26 1989 Region 7 Texas Air Control Board

Texas Air Control Board 6330 Hwy 290 East Austin, Texas 78723

Attention: Bill Stewart, P.E.

Executive Director

Subject:

Permit Exemption X-3561 Barge Cleaning Facility Freeport, Brazoria County

Dear Mr. Stewart:

As of January 20, 1989, Hercules Offshore Drilling Company acquired Fish Engineering & Construction, Inc. Marine Yard in Freeport, Texas.

We hereby request transfer of this registration to Hercules Offshore Drilling Company and agree to the existing terms and conditions of this registration.

Respectfully,

William Coward

President

WC/se

cc: Mr. Hunt

5555 West Loop, Suite 300 Bellaire, Texas 77401

Strength through experience, equipment, know-how 11381 Meadowglen Lane 

Houston, Texas 77082 (713) 497-7934

January 25, 1989

RECEIVED JAN 26 1989 Region 7 Texas Air Control Board

Texas Air Control Board 6330 Hwy 290 East Austin, Texas 78723

Attention: Bill Stewart, P.E.

Executive Director

Subject:

Permit Exemption X-3561 Earge Cleaning Facility Freeport, Brazoria County

Dear Mr. Stewart:

As of January 20, 1989, Hercules Offshore Drilling Company acquired Fish Engineering & Construction, Inc. Marine Yard in Freeport, Texas.

We hereby request transfer of this registration to Hercules Offshore Drilling Company and agree to the existing terms and conditions of this registration.

Respectfully,

William Coward

President

WC/se

cc: Mr. Hunt

5555 West Loop, Suite 300 Bellaire, Texas 77401

Strength through experience, equipment, know-how 11381 Meadowglen Lane D. Houston, Texas 77082 (713) 497-7934

January 25, 1989

JAN 26 1989

Region 1 Texas Air Control Board

Texas Air Control Board 6330 liwy 290 East Austin, Texas 78723

Attention: Bill Stewart, P.E.

Executive Director

Subject:

Permit Exemption X-3561

Earge Cleaning Facility Freeport, Brazoria County

Dear Mr. Stewart:

As of January 20, 1989, Hercules Offshore Drilling Company acquired Fish Engineering & Construction, Inc. Marine Yard in Freeport, Texas.

We hereby request transfer of this registration to Hercules Offshore Drilling Company and agree to the existing terms and conditions of this registration.

Respectfully,


William Coward

President

WC/se

cc: Mr. Hunt

5555 West Loop, Suite 300 Bellaire, Texas 77401





FEB 14 1989



President President HERCYLES OFFSHORE ORILLING COMPANY 11301 Peerowglun Lane Houston, Texas 77082

1

formerly Fish Engineering Changefile lubels

Re: Change of Demership Permit No. X-13561 Sarge Cleaming Freedort, Brazonia County Account 16 No. BL-6118-V

Dear Er. Coward:

We appreciate being informed that Hercules Offshore Brilling Company is the new owner of the referenced facility which was previously owned by Fish Engineering and Construction, Incorporated. Our files have been upuated to indicate that the change of ownership has occurred.

We understand that there will be no change in the type of pollutants emitted and no increase in the quantity of emissions. You are reminded that the facility must be in compliance with all Rules and Regulations of the Texas Air Control Board and the requirements of this permit exemption at all times.

Thank you for this information and for your commitment to comply. Your cooperation and interest in air pollution control are appreciated.

#### ORIGINAL SIGNED BY LE PEWATT

Lawrence E. Pewitt, P.E. Director, Permits Division

cc: Vir. Herbert W. Williams, Jr., Regional Director, Houston
Leo D. O'Gorman, M.D., Director, Brazoria County Health Department,
Angleton
Mr. Tom Randolph, Fish Engineering and Construction, Incorporated,
Houston

FEB 14 1989



S. 79- in section

ion. William Coward Tresident HERCULES GEESHORE ORILLING COMPANY 11301 Mesconglen Lane Houston, Texas 77982

formerly
Fish Engineering
Changefile lubols

Re: Change of Ownership C Permit No. X-13561 Barge Cleaning Freeport, Brazoria County Account 10 No. RL-6118-V

Gear Sr. Coward:

We appreciate being informed that Hercules Offshore Brilling Company is the new owner of the referenced facility which was previously owned by Fish Engineering and Construction, Incorporated. Gur files have been upualed to indicate that the change of ownership has occurred.

We understand that there will be no change in the type of pollutants emitted and no increase in the quantity of emissions. You are reminded that the facility must be in compliance with all Rules and Regulations of the Texas Air Control Board and the requirements of this permit exemption at all times.

Thank you for this information and for your commitment to comply. Your comperation and interest in air pollution control are appreciated.

#### ORIGINAL SIGNED BY LE PEWIT

Lawrence E. Pewitt, P.E. Director, Permits Division

cc: Vir. Herbert W. Hilliams, Jr., Regional Director, Houston Leo D. O'Gorman, M.D., Director, Brazoria County Health Department, Angleton Mr. Tom Randolph, Fish Engineering and Construction, Incorporated, Houston

# **∃Violation**

## □VIOLATIO FOLLOWUP

-	Þ
4	7-

		,
$\mathbf{\nabla}$	Add	
$\overline{}$	5.	nqe
=		_
Щ	ter	ete

### INVESTIGATION/VIOLATION FORM

DISTRIBUTION: 2 Blue - Region/Local Program Canary - Data Entry/Region

	☐ Delete	(BOLDFACED ITEMS ARE REQUIRED)	Pink - Investigator/Data Entry
1	Primary Investigator Juriscode Site Name/Location: Free	Account Name: Fish Enginery) 08889 Off Hours (Y or 1 Permit(s): 010 Other Juriscode 1 Other Juriscode	her Juriscode 2 V
2	Federal Program (Y or N): NSP Investigation Type FILE I Comment FILE REVIEW  * * * FOR RECORD Date Test Conducted (as MMDDYY	ARelated Previous Investigation  SINESHAP Situation Number  THOUSE Investigation (Y or N) Y **EP  For Client - SCE NOT  OLLOW  Date Report Received (A)  Permit(s):	(COMPLIANCE DIV. ONLY) N C
3	Federal Program (V or N) NSP	Related Previous Investigation S_NESHAP_Situation Number_ n-House Investigation (Y or N)	(COMPLIANCE DIV. ONLY)
4	Cause/Description Rule Violated Fill in the Following Applia Permit Number Board Order Number *FIN Involved	CPS/DELETES ONLY) Situation Number  (Co)  Contamcode  cable Items:  Permit Provision  Court Order Number  Facility Name (optional)  N=Non-Clerical, I=Imminent Danger)	MPLIANCE DIV. ONLY)   CFR Part
4	Cause/Description Rule Violated Fill in the Following Applia Permit Number Board Order Number *FIN Involved	Contamcode  Cable Items: Permit Provision Court Order Number Facility Name (optional) N=Non-Clerical, I=Imminent Danger)	MPLIANCE DIV. ONLY)   CFR Part
-	*SEE BACK FOR VALID CODES AND **EPN REQUIRED FOR INVESTIGATION *FIN REQUIRED FOR VOC VIOLATION	INVESTIGATION TYPE CODES MATRIX N TYPES INDICATED ON BACK WITH AN * NS AS INDICATED WITH A + IN THE USER':	
	Investigator Signature:		Date: 3 8 89
	Approved By: LL Screen ID: IV1, IV11, VL1		Date: 3 % %5 ACB 93A (12/1/87)
			T&E 000406

Cc: Dustin Complians 3-8-89

Paul Hant to Mickey Timer - Hercules of shore Freeport BL-0016-14 Formuly Fiel Engineering

mickey called me on 3-6-89, and questioned to permit states: specifically her felt his facility would have over 101 TPY emissions VOC. His promit is for 17.4 7 PY. That's Permit Exemplies x-3561. I reviewed the file, discussed it with Pill Kivie, and called minkey back today. The 17.4 TPY refere to emissions in his Plant site. 90% of his Barge Cleaning of voc. To conducted over the Bary land. Therefore They emissions are spenget. I centioned Sim, though, about the potential for muisance Dust and odor from abrasive cleaning, and from Barge holes and cleaning solvents. He said he would sheet down when ever winds might carry nuisance Dust or Voc adore to nearby I Told him TACB residents. fooded likely conduct a full SIP within a year. (I recommend we do so.) name chance was cut feel Thunt & & 000407

			<del>-</del>
	VIOLATION	□VIOLATION I	100
	<b>♥</b>		DISTRIBUTION: 6/25/87
	Add .	INVESTIGATION/VIOLATION FORM	Blue - Region/Local Program
	Change	(BOLDFACED ITEMS ARE REQUIRED)	Canary - Data Entry/Region
	Delete		Pink - Investigator/Data Entry
٠,٠	51 11101	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	وهن بيان د کارونونو هر ديد ايد ا <b>ند. د. د.</b>
	Account Number 15 0 1/8 (	Account Name: Tecule	S OFFSHORE
	Date of Investigation (as MADDY	Y) 04/289 Off Hours (Y	( or N)
4	Investigator Staffcode wp/	Account Name: 1/2-cule Y) 04/2-9 Off Hours (Y Permit(s): 2) Other Juriscode 1	
Ţ	Primary Investigator Juriscode	Other Juriscode I	Other Juriscode 2 _V
	Site Name/Location:	CONT	
	Person Contacted/Phone:	ICKEY FINER	#WVS TON 229-822
			4 NT1
	Investigation Number 335860	2 4 Related Previous Investigat	ion Number
	rederal Program (Y or N): NSPS	NESHAP Situation Number	(COMPLIANCE DIV. ONLY)
	Investigation Type Car In	House Investigation (Y or N)	EPN
	comment complaint	0782-00110	resource /
9	ada MIT CA	franced	1/
4	_	NG REVIEWS OF COMPANY-SUBMITTED R	** * * * NT.Y * * *
	Date Test Conducted (as MMDDYY)		
	·		
	Analysis Review Results (C,N,U)	Permit(s):	Retest Required?
	Investigation Number	Related Previous Investigat	ion Number
	Federal Program (V or NT+ NSDS	MESHAD Situation Number	(COMPLIANCE DIV. ONLY)
9	*Investigation Type In	-House Investigation (Y or N)	*EPN
J	Comment		
	Investigation Number		l Ordinance (Y or N)
		ES/DELETES ONLY) Situation Number	
	Cause/Description (Crand		(COMPLIANCE DIV. ONLY)
	Rule Violated	Contamo	-
	Fill in the Following Applic	able Items	
4	Permit Number	Permit Provision	
-	Board Order Number	Court Order Number	CFR Part
	*FIN Involved	Facility Name (ontional)	
	Violation Type (C=Clerical.	Permit Provision Court Order Number Facility Name (optional) N=Non-Clerical, I=Imminent Dange	r)
	Date NOV Received (as MMDDYY)	(DEFAULTS TO 5 DAYS	AFTER DATE NOV SENT)
	Investigation Number	Loca ES/DELETES ONLY) Situation Number	1 Ordinance (Y or N)
	Cause/Description (CHARCE	ENAPERATES CHIEF SECURITION NUMBER	(COMPLIANCE DIV. CMP)
	Rule Violated	Contamo	ye //www.nrawes nra- manri
_	Fill in the Following Applic	able Items:	
4	Permit Number	Permit Provision	
_	Board Order Number	Court Order Number	CFR Part
	*FIN Involved	Permit Provision Court Order Number Facility Name (optional) N=Non-Clerical, I=Imminent Dange	
	Violation Type (C=Clerical.	N-Non-Clerical, I=Imminent Dance	r)
	Data WY Cast (at 1880MX)		
	Date NOV Received (as MMDDYY)	(DEFAULTS TO 5 DAYS	AFTER DATE NOV SENT)
	SEE BACK FOR VALID CODES AND I		<b>4</b> .
		TYPES INDICATED ON BACK WITH AN	
		S AS INDICATED WITH A + IN THE US	ER'S MANUAL RULE TABLE
	Investigator Signature:	m/ Hunt	Date: 5-9-89
		Charles and the second	Date: 5-9-89  Date:
	Approved By:		<del></del>
	Screen ID: IVI, IVII, VLI	Page of Pages E 0(	)0408 ACB 93A (12/1/87)

<u>Subject</u>: Complaint 078900110 was received by the Region 7 office on April 5, 1989, and alleged that nuisance fumes from Hercules Offshore's barge cleaning operation were causing the complainant to have a runny nose and chest pains. Mr. Robby Blair, inspector for the City of Freeport referred the complaint to Region 7 and accompanied me on the investigation.

Investigative Findings: We arrived at the complainant's residence on April 12, 1989, at 9:35 a.m. The complainant has complained on this source in the past but nuisance has not been confirmed. He says Hercules opens barge hatches at night, allowing the fumes to drift over his home in the stable morning atmosphere. He requested information on Benzene from TACB and I referred him to Austin, Health Effects Division.

At 9:55 a.m. we met with Mr. Mickey Tiner, manager of Hercules' marine division. Mr. Tiner said that Hercules does not open barges prior to 8:00 a.m. and showed records for the several day period when the complaint was received which appeared to verify this statement. Nuisance odor was not confirmed at this time. Mr. Tiner conducted a short plant tour and invited us to come back at any time.

Recommendations: While I observed no nuisance odor during this investigation, the potential for nuisance conditions is present. The source of these nuisance conditions could be either Hercules Offshore's facility, miscellaneous barge traffic, some other as yet undetermined stationary source, or any combination of the above. More complaints from this area are likely. I recommend 1) utilize Mr. Blair's department with the City of Freeport as much as possible since he can respond much sooner than Region 7 and may be able to give us some input into the problem that would be lost to us due to the lengthy response time for us; and 2) that Region conduct an SIP investigation into the entire facility. An SIP is important because Hercules has moved another division onto the existing site which conducts maintenance on offshore rigs. I have no evidence to indicate that it is a permitted facility. Also, emissions from the barges are ducted into a landbased filtration system and may need to be included in the total emissions for the barge cleaning facility. Hercules is still a grandfathered source, but I believe that the ducting and filtering of these emissions was not a part of the original operation. If so, the barge cleaning facility may need to be permitted.

RK

Son

Paul Hunt Environmental Quality Specialist Region 7 File: 04895860.wph

# □ VIOLATION FOLLOWUP **™VIOLATION** ) Delete Blue - Region/Local Program ACCOUNT FORM Canary - Data Entry/Region (BOLDFACED ITEMS ARE REQUIRED) Pink - Investigator/Data Entry Account Number BLD118V Jurisdiction 170 \*Account Status (AA, IA, DA) Mailing Midress 1 PD Box 22535 1381 Meaning landung \_\_\_\_ Mail Zip 7706982\_ Mail: City Location (Enter location in "Comment Entries" below with '15' as the code) Exceptite \_\_\_\_ Location Zip 77541 SIC 4491 \_\_ Milkey Tiner\_\_\_\_\_ -Significant Contaminants--Portable Account (Y or N) N Federal (Y or N) Contam Code **Amount** \*TSP Attain Status (A, N, U) A PARTICULATE \*Class (UK, DR) Lik (Add Only) **S**O<sub>2</sub> Sch.Inv.Mo. (1-12) Previous Location (Y or N) \*Code Line+ Account Comment \*SEE BACK FOR VALID CODES TLINE NUMBER REQUIRED TO CHANGE OR DELETE A PREVIOUSLY ENTERED ACCOUNT COMMENT Investigator Signature: Approved By: Screen ID: AC2, AC3, ACC1 ACB 92 (12/1/87)

	: UVIOLATION		FOLLOWUP D.P
	Change ( Delete	INVESTIGATION/VIOLATION FORM BOLDFACED ITEMS ARE REQUIRED)	DISTRIBUTION: 7/12/8 Blue - Region/Local Program Canary - Data Entry/Region Pink - Investigator/Data Entry
1		Off Hours (Y Permit(s):  Off Hours (Y Permit(s	Other Juriscode 2
2	Investigation Number 3 354 16 Federal Program (Y or N): NSPS 1 Investigation Type & COSV In- Comment Long. N. D784 Op.	P NESHAP N Situation Number House Investigation (Y or N) 7	EPN
3	Investigation Number Federal Program (Y or N): NSPS Investigation Type In- Comment	Related Previous Investigat	ion Number
4	Cause/Description Rule Violated Fill in the Following Applica	Contamed  ble Items:  Permit Provision  Court Order Number  Facility Name (optional)  N=Non-Clerical, I=Imminent Dange	(COMPLIANCE DIV. ONLY)  cde CFR Part  er)
4		S/DELETES CNLY) Situation Number  Contamod  ble Items:  Permit Provision  Court Order Number  Facility Name (optional)  N=Non-Clerical, I=Imminent Dange	(COMPLIANCE DIV. CNLY)  cde   CFR Part
		TYPES INDICATED ON BACK WITH AN AS INDICATED WITH A + IN THE US	ER'S MANUAL RULE TABLE  Date:
			Date: 1/1/1/1
	Screen ID: IV1, IVI1, VL1	Page 1 of 3 Pages	100416 ACB 93A (12/1/87)

BL-0118-V 5/17/89 Page 3

<u>Subject:</u> On 5/17/89 complaint 078900151 was investigated. The complainant complained of benzene odors in the early morning hours from barge cleaning activities at Hercules Offshore.

Discussion: I arrived at this site at 4:00 p.m. on 5/17/89. Winds were from the east and southeast at 5-10 mph. I stopped at the complainant's residence but no one was home. conducted an odor survey downwind of the Hercules facility and did not find any significant odors. I discussed the complaint with Mr. Buddy Dunn, of Hercules, who identified the complainant. He said that it had been company policy since the complainant had started complaining not to clean barges when there is a north wind. A northerly wind would blow odors in the complainant's direction. I later talked with Mr. Mickey Tiner, manager at Hercules, who confirmed that policy.

Summary: I did not find nuisance odors coming from Hercules Offshore during this investigation. Company personnel claim that barges are not cleaned during northerly winds which would impact the complainant.

Environmental Quality Specialist Region 7

Filename: 05895916A.lrp

## REQUEST TO DELETA

SOURCE ACCOUNT: ACCOUNT TO BE DELETED)  "ACCOUNT NO: BL-OOLG-H CO. NAME: Fish Engineering and Construction  COUNTY: Brazoria LOCATION: Treeport  TARGET ACCOUNT: (VALID ACCOUNT)  ACCOUNT NO: BL-OHB-V CO. NAME: Hercales Offshore Dilling Co.  COUNTY: Brazoria LOCATION: Treeport  REASON(S) FOR DELETION:  CO. BUYOUT ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Deginal Compune Fish Engineering had two account numbers for one smooth Numbers obtained had two account numbers for one smooth Numbers should be deleted Brooth and BL-OHB-V are deplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lanc Treeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP?  IF YES, WHO IS THE OWNER? Hercules DEFisher Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN THE DATABASE AS DOCUMENTED UNLESS AN ACCOUNT CHANGE FORM IS	REQUESTED BY: Larry Priddy DATE: 615189
TARGET ACCOUNT: (VALID ACCOUNT)  ACCOUNT NO: BL-OUR-V CO. NAME: Hercules Officer Dilling Co.  COUNTY: Brazoria LOCATION: Treport  REASON(S) FOR DELETION:  CO. BUYOUT ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Logical Company - Fish Engineering load two account numbers for one swater. Unreades Defisher acquired Fish Engineering and Deletic Bleonates numbers should be depleted. Bleonate and Bleonate account and the target account located at the same geographical location? Yes  WHAT IS THAT LOCATION? Warlin Lawe Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules Defisher Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	
TARGET ACCOUNT: (VALID ACCOUNT)  ACCOUNT NO: BL-O118-V CO. NAME: Hercules Officer Dilling Co.  COUNTY: Brazoria LOCATION: Trepport  REASON(S) FOR DELETION:  CO. BUYOUT ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Digital Company - Fish Engineering had two account numbers for one sometic. Uncerted Defisher acquired Fish Engineering and data of the Albertal Bl-oole-H and Bl-o118-Vare duplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Worlin Lane Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes, WHO IS THE OWNER? Hercules Offshore Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	ACCOUNT NO: BL-OOLG-H CO. NAME: Fish Engineering and Constru
ACCOUNT NO: BL-OHR-V CO. NAME: Hercales Offshore Dilling Co. COUNTY: Brazoria LOCATION: Treport  REASON(S) FOR DELETION:  CO. BUYOUT ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Digital Compuny - Fish Engineering load two account numbers for one sometic. Uncertes Defishers acquired Fish Engineering and one of the accounts numbers should be deleted. Be-ooth-W and BL-OHB-V are duplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION?  WHAT IS THAT LOCATION? Marlin Lane Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY?  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP?  Les Laccount Information for the Target Account Will Appear in	COUNTY: Brazoria LOCATION: Freeport
REASON(S) FOR DELETION:  CO. BUYOUT ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Loginal (Impuny - Fish Engineering land two account mambers for one sometime Unreales Dffshree acquired Fish Engineering and day of the accounts numbers should be deleted. Be-ook-H and Be-oile-V are duplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lane Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules Offshere Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	·
REASON(S) FOR DELETION:  CO. BUYOUT ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Loginal (Impuny - Fish Engineering land two account mambers for one sometime Unreales Dffshree acquired Fish Engineering and day of the accounts numbers should be deleted. Be-ook-H and Be-oile-V are duplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lane Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules Offshere Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	ACCOUNT NO: BL-0118-y CO. NAME: Harches Office Dilling Co.
ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Digital Company - Fish Engineering had two account numbers for one somether. Unrules Dffshow acquired Fish Engineering and one of the accounts numbers should be deleted. Be-ook-y and Be-our-vare duplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lane Freport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules Dffshore Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	COUNTY: Brazoria LOCATION: Freeport
ACCOUNT ADDED IN ERROR  PLEASE EXPLAIN: Digital Company - Fish Engineering had two account numbers for one somether. Unrules Dffshow acquired Fish Engineering and one of the accounts numbers should be deleted. Be-ook-y and Be-our-vare duplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lane Freport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules Dffshore Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	" DEACON(C) FOR RELEMION.
PLEASE EXPLAIN: Digital Company - Fish Engineering had two account numbers for one source. Herebes Deeshor acquired Fish Engineering and one of the accounts numbers should be deleted. Be-oold-Hand Be-oile-Vare deplicate accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lane Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules Deeshore Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	·
numbers for one source because Deepher acquired fish Engineering and one of the accounts numbers should be deleted. Be-ooth-H and Be-oile-V are deplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lane Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Wescales Defisher Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	
and bry of the alcounts numbers should be deleted. BL-0016-W and BL-0118-V are duplicate Accounts  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED AT THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lane Freeport  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules Defisher Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	
THE SAME GEOGRAPHICAL LOCATION? Yes  WHAT IS THAT LOCATION? Marlin Lawe Freeport  ARE BOTH THE SCURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules DEFisher Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	and one of the accounts numbers should be deleted. BL-0016-6 and BL-0118-V are duplicate Accounts
WHAT IS THAT LOCATION? Marlin Lane Freeport  ARE BOTH THE SCURCE ACCOUNT AND THE TARGET ACCOUNT LOCATED ON CONTIGUOUS PROPERTY?  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING UNDER A SINGLE OWNERSHIP?  Less Defining Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	A-
CONTIGUOUS PROPERTY? Yes  ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING  UNDER A SINGLE OWNERSHIP? Yes  IF YES, WHO IS THE OWNER? Hercules DEFshare Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	
IF YES, WHO IS THE OWNER? Hercules DEFshore Drilling Company  ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	· · · · · · · · · · · · · · · · · · ·
ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	ARE BOTH THE SOURCE ACCOUNT AND THE TARGET ACCOUNT OPERATING
ALL ACCOUNT INFORMATION FOR THE TARGET ACCOUNT WILL APPEAR IN	under a single ownership? <u>Ves</u>
	IF YES, WHO IS THE OWNER? Hercules DEEshore Drilling Compan
THE DATABASE AS DOCUMENTED UNLESS AN ACCOUNT CHANGE FORM IS	
	THE DATABASE AS DOCUMENTED UNLESS AN ACCOUNT CHANGE FORM IS

پ پیر	VIOLATION VIOLATION FOLLOWUP
	Add Change Change Delete  Distribution: Blue - Region/Local Program Canary - Data Entry (logibil) Pink - Investigator/Data Entry
1	Account Number BLD118V Account Name: Hercules Offshore  Date of Investigation (as MMDDYY) 08 09 89 Off Hours (Y or N)  Investigator Staffcode MAKI Permit(s):  Primary Investigator Juriscode 070 Other Juriscode 1 Other Juriscode 1  Site Name/Location: 906 Martin   Free port  Person Contacted/Phone: Jimmy Tarkson 409 - 233-6371
2	Investigation Number 33 66/5A Related Previous Investigation Number Federal Program (Y or N): NSPS NESHAP Situation Number (COMPLIANCE DIV. ONEX) *Investigation Type Cosy In-House Investigation (Y or N) N*EPN  Comment Compl. INV. In Despoyse to 018900250  * * * FOR RECORDING REVIEWS OF COMPANY-SUBMITTED REPORTS ONLY * * *
	Date Test Conducted (as MMDDYY) Date Report Received (as MMDDYY) Analysis Review Results (C,N,U) _ Permit(s): Retest Required?
3	Investigation Number 3 3 66 15 B Related Previous Investigation Number Federal Program (Y or N): NSPS NESHAP Situation Number (COMPLIANCE DIV. ONLY) 'Investigation Type PMAP In-House Investigation (Y or N) N *EPN Comment
4	Investigation Number 33 66/5 A Local Ordinance (Y or N)  Violation Number OCC (CHANGES/DELETES ONLY) Situation Number (COMPLIANCE DIV. ONLY)  Cause/Description Yulisante Prohibition (COMPLIANCE DIV. ONLY)  Rule Violated 101.44 Contamcode 14570  Fill in the Following Applicable Items:  Permit Number Permit Provision  Board Order Number Court Order Number CFR Part  *FIN Involved Facility Name (optional)
	Violation Type (C-Clerical, N-Non-Clerical, I-Imminent Danger) Date NOV Sent (as MMDDYY) 091989 Date NOV Received (as MMDDYY) (DEFAULTS TO 5 DAYS AFTER DATE NOV SENT)
4	Investigation Number 3366/5/†  Violation Number 000 2 (CHANGES/DELETES ONLY) Situation Number (COMPLIANCE DIV. ONLY Cause/Description Air Pollyfor Problems (COMPLIANCE DIV. ONLY)  Rule Violated 4.0/4 TC/HA Contamode 14570  Fill in the Following Applicable Items:  Permit Number Permit Provision  Board Order Number Court Order Number OFR Part  *FIN Involved Facility Name (optional)
	Violation Type N (C-Clerical, N-Non-Clerical, I-Imminent Danger)  Date NOV Sent (as MMDDYY) 091959  Date NOV Received (as MMDDYY) (DEFAULTS TO 5 DAYS AFTER DATE NOV SENT)
	*SEE BACK FOR VALID CODES AND INVESTIGATION TYPE CODES MATRIX  **EPN REQUIRED FOR INVESTIGATION TYPES INDICATED ON BACK WITH AN *  *FIN REQUIRED FOR VOC VIOLATIONS AS INDICATED WITH A + IN THE USER'S MANUAL RULE TABLE
	Investigator Signature: Mary a. Knotts Date: 8/23/89
	Approved By: Date:
	Screen ID: IV1, IV11, VLI Page of Pages 000057 ACB 93A (12/1/87)

BL-0118-V 8/9/89 Page 3

Purpose: This investigation was conducted in response to complaint No. 078900250 alleging nuisance dust from sandblasting and a choking chemical odor caused by Hercules Offshore, a neighboring barge cleaning and refurbishing operation. The complaint was received at approximately 2:10 p.m. on July 31, 1989.

investigative Findings: At approximately 10:05 a.m. on August 9, 1989, Dwayne Meckler and I arrived in the vicinity of the complainant's residence and the Hercules Offshore facility. Sandblasting was being conducted on a barge at the Hercules facility (see attached photos) The dust was observed leaving the facility and traveling in a westerly direction towards the complainant's residence. The wind speed was 7-to 10 mph from a northeastly direction (45-degrees NE) --- A visit was made to the complainant's residence. At approximately 10:20 a.m. we arrived at the residence. The dust from the sandblasting made it extremely uncomfortable for both Dwayne and I to breath. Inside the complainant's house it was better. I spoke with the complainants (husband and wife). They stated that the sandblasting had been going on since the previous day, only on that day the blasting was being done on a barge that was located on the west side of the facility and closer to their residence. The complainant said that the dust was so bad that they had to leave home. They stated that at this time they could just stay inside with the windows closed. The wind was from the same northeasterly wind direction. The complainants stated that the neighboring facility had been causing problems for a number of years. The problems alleged were: dust from sandblasting and the venting off of the chemical barges containing vaporous compounds (such as benzene, styrene and The complainants were concerned that with a other things). newsgrandchild on the way (which they expect to be caring for) that there may be danger from breathing the pollution. They recounted an incident that occurred about a year ago where styrene fumes were vented during the night while everyone was sleeping with the windows open. The fumes filled the house and everyone woke up coughing and choking. The fumes were alleged to have killed a tree and other vegetation. facility was taken over by Hercules about a year and a half ago.

A change of ownership from Fish Engineering was submitted on January 25, 1989 and acknowledged by Lawrence Pewitt, Director, Permits Division Austin, on February 14, 1989 (letters in regional company file).

Upon leaving the complainant's residence a coat of fine dust (which was not there before we entered the residence) had accumulated on the state car. The dust again made it uncomfortable for us to breath. It was 11:30 a.m. and the sandblasting was still going on. The wind was still from the northeast.

Asvisit was made to the Hercules Offshore facility where we spoke with Jimmy Jackson, Craft Supervisor. Mr. Jackson was informed of the complaint against the facility. Mr. Jackson stated that the complaints from the neighbor (located to the west of the facility) were ongoing. He reported that the neighbor complains about everything from odors to the noise that a passing private boat makes. Mr. Jackson provided us with a tour of facility. At the middle of the facility on the south side there were four workers sandblasting a barge which created a tremendous amount of dust. I asked Mr. Jackson if that much sandblasting was the normal amount of activity. He stated that usually there are two workers but this job had to be finished sooner than anticipated. approximately 11:50 a.m. the sandblasting stopped apparently because it was lunchtime. The sandblasting was observed for one hour and 45 minutes. I asked Mr. Jackson if he could see that dust was being blown towards the houses located to the west of the plant, could be causing a problem. He answered I informed Mr. Jackson that we observed a significant amount of fine dust downwind of the sandblasting. This dust amounted to a nuisance and a violation of Board Rule 101.4 and compliance was requested.

The facility was built in the early 1950's. A TACB special exemption (Exemption X-3561) was issued 5/8/82 for a barge cleaning facility expansion by the previous owner, Fish Engineering, but due to economic conditions tankage increases did not occur and the expansion was not initiated except for the installation of a hot water heater. The sandblasting operation was grandfathered.

During the tour, moderate odors were observed near the barge cleaning and gas-freeing section of the plant. No odors were observed off plant property, however. There was a barge waiting to be cleaned which had been use to transport styrene.

Mr. Jackson stated that they were waiting for the right wind direction to de-gas the barge. He said that they made the barges gas-free when the wind was blowing away from the residences. There were no means for controlling vapors from

BL-0118-V 8/9/89 Page 5

the barges. The only means of avoiding nuisance odor from the gas-freeing operation is noting the wind direction. Due to the high potential for nuisance associated with the gas-freeing operating of the barges, sampling is recommended when this activity is being conducted.

The complainants were informed of the investigative findings and recommendations regarding the complaint. They were also encouraged to contact the regional office should the conditions recur.

Conclusion: Hercules Offshore Company will be issued a Notice of Violation for Board Rule 101.4, which consisted of nuisance dust from the sandblasting of a barge. This dust was in such concentration and duration as to adversely affect the breathing and to interfere with the normal use and enjoyment of the property of residents downwind of the sandblasting. No enforcement action is recommended pending receipt and review of a requested written response from the company.

No nuisance odors were detected at the time of the investigation, however, due to the high potential for nuisance when the barge venting and gas-freeing operation is being conducted, sampling is recommended to assess health affects and/or hazards.

Mary A! Knotts

Environmental Quality Specialist

Region 7

Filename: 08896615.mak

	_ ENIOLATION	LVIUL	n n	"ULLUWUP()
بن.	-			D.Y
-	ÇCQ	INVESTIGATION/VIOLA BOLDFACED ITEMS ARE		DISTRIBUTION: Blue - Region/Local Program  Canary - Data Entry (Jogie)  Pink - Investigator/Hata Entry
1	Account Number BLD118V Date of Investigation (as MMDDYY Investigator Staffcode MAKI Primary Investigator Juriscode Site Name/Location: 906 M Person Contacted/Phone: Trim	o 70 Other Juriso	ode l	Other Juriscode
9	Investigation Number 33 6615 Federal Program (Y or N): NSPS Investigation Type COS V In- Comment Compl. INV. in	House Investigation	(YORN) 🔥	**EPN
2.	* * * FOR RECORDING Date Test Conducted (as MMDDYY)			REPORTS CNLY * * * ved (as MMDDYY)
	Analysis Review Results (C,N,U)		-	
3	Investigation Number 3 3 66 15 Federal Program (Y or N): NSPS *Investigation Type PMAP In- Comment	Related Previo	ous Investiga on Number (Y or N) X	(COMPLIANCE DIV. ONLY)
4	Investigation Number 3366/ Violation Number OCO (CHNNE) Cause/Description Yulisants Rule Violated 101.4  Pill in the Following Application Permit Number Board Order Number *FIN Involved Violation Type A (C-Clerical, Date NOV Sent (as MMDDYY) 99/ Date NOV Received (as MMDDYY)	Problems: Permit Provision Court Order Number Facility Name (constant)	Contamo  Contamo  Experional)	(COMPLIANCE DIV. ONLY)  code 14570  CHR Part  ger)
4	Investigation Number 3366/3 Violation Number 000 2 (CHANGE Cause/Description Air Polly! Rule Violated 4,0/4) Tc/Fill in the Following Application Permit Number Board Order Number  *FIN Involved Violation Type / (C=Clerical, in Date NOV Sent (as MMDDYY) 09/1 Date NOV Received (as MMDDYY)	S/DELETES ONLY) Site of Problems: Permit Provision Court Order Number Facility Name (content of the content of	Contamo	COMPLIANCE DIV. ONEY)  Code 14570  OR Part
	*SEE BACK FOR VALID CODES AND IN **EIN REQUIRED FOR INVESTIGATION **FIN REQUIRED FOR VOC VIOLATIONS	TYPES INDICATED ON AS INDICATED WITH	BACK WITH AN A + IN THE U	
	Investigator Signature: 1000	y U. Knotts		Date: 1/23/89
	Approved By:	•	<u> </u>	Date:
	Screen ID: IVI, IVII, VLA	Page of P	ages T	E 000410 93A (12/1/87

Purpose: This investigation was conducted in response to complaint No. 078900250 alleging nuisance dust from sandblasting and a choking chemical odor caused by Hercules Offshore, a neighboring barge cleaning and refurbishing operation. The complaint was received at approximately 2:10 p.m. on July 31, 1989.

investigative Findings: At approximately 10:05 a.m. on August 9, 1989, Dwayne Meckler and I arrived in the vicinity of the complainant's residence and the Hercules Offshore facility. Sandblasting was being conducted on a barge at the Hercules facility (see attached photos). The dust was observed leaving the facility and traveling in a westerly direction towards the complainant's residence. The wind speed was 7 to 10 mph from a northeastly direction (45 degrees NE). A visit was made to the complainant's residence. At approximately 10:20 a.m. we arrived at the residence. The dust from the sandblasting made it extremely uncomfortable for both Dwayne and I to breath. Inside the complainant's house it was better. I spoke with the complainants (husband and wife). They stated that the sandblasting had been going on since the previous day, only on that day the blasting was being done on a barge that was located on the west side of the facility and closer to their residence. The complainant said that the dust was so bad that they had to leave home. They stated that at this time they could just stay inside with the windows closed. The wind was from the same northeasterly wind direction. The complainants stated that the neighboring facility had been causing problems for a number of years. The problems alleged were: dust from sandblasting and the venting off of the chemical barges containing vaporous compounds (such as benzene, styrene and The complainants were concerned that with a other things). new grandow on the way (which they expect to be caring for) that there may be danger from breathing the pollution. They recounted an incident that occurred about a year ago where styrene fumes were vented during the night while everyone was sleeping with the windows open. The fumes filled the house and everyone woke up coughing and choking. The fumes were alleged to have killed a tree and other vegetation. facility was taken over by Hercules about a year and a half ago.

A change of ownership from Fish Engineering was submitted on January 25, 1989 and acknowledged by Lawrence Pewitt, Director, Permits Division Austin, on February 14, 1989 (letters in regional company file).

Upon leaving the complainant's residence a coat of fine dust (which was not there before we entered the residence) had accumulated on the state car. The dust again made it uncomfortable for us to breath. It was 11:30 a.m. and the sandblasting was still going on. The wind was still from the northeast.

A visit was made to the Hercules Offshore facility where we spoke with Jimmy Jackson, Craft Supervisor. Mr. Jackson was informed of the complaint against the facility. Mr. Jackson stated that the complaints from the neighbor (located to the west of the facility) were ongoing. He reported that the neighbor complains about everything from odors to the noise that a passing private boat makes. Mr. Jackson provided us with a tour of facility. At the middle of the facility on the south side there were four workers sandblasting a barge which created a tremendous amount of dust. I asked Mr. Jackson if that much sandblasting was the normal amount of activity. He stated that usually there are two workers but this job had to be finished sooner than anticipated. approximately 11:50 a.m. the sandblasting stopped apparently because it was lunchtime. The sandblasting was observed for one hour and 45 minutes. I asked Mr. Jackson if he could see that dust was being blown towards the houses located to the west of the plant, could be causing a problem. He answered I informed Mr. Jackson that we observed a significant amount of fine dust downwind of the sandblasting. This dust amounted to a nuisance and a violation of Board Rule 101.4 and compliance was requested.

The facility was built in the early 1950's. A TACB special exemption (Exemption X-3561) was issued 5/8/82 for a barge cleaning facility expansion by the previous owner, Fish Engineering, but due to economic conditions tankage increases did not occur and the expansion was not initiated except for the installation of a hot water heater. The sandblasting operation was grandfathered.

During the tour, moderate odors were observed near the barge cleaning and gas-freeing section of the plant. No odors were observed off plant property, however. There was a barge waiting to be cleaned which had been use to transport styrene.

Mr. Jackson stated that they were waiting for the right wind direction to de-gas the barge. He said that they made the barges gas-free when the wind was blowing away from the residences. There were no means for controlling vapors from

BL-0118-V 8/9/89 Page 5

the barges. The only means of avoiding nuisance odor from the gas-freeing operation is noting the wind direction. Due to the high potential for nuisance associated with the gas-freeing operating of the barges, sampling is recommended when this activity is being conducted.

The complainants were informed of the investigative findings and recommendations regarding the complaint. They were also encouraged to contact the regional office should the conditions recur.

Conclusion: Hercules Offshore Company will be issued a Notice of Violation for Board Rule 101.4, which consisted of nuisance dust from the sandblasting of a barge. This dust was in such concentration and duration as to adversely affect the breathing and to interfere with the normal use and enjoyment of the property of residents downwind of the sandblasting. No enforcement action is recommended pending receipt and review of a requested written response from the company.

No nuisance odors were detected at the time of the investigation, however, due to the high potential for nuisance when the barge venting and gas-freeing operation is being conducted, sampling is recommended to assess health affects and/or hazards.

Mary A. Knotts

Environmental Quality Specialist

Region 7

Filename: 08896615.mak

		UVIOLATION F	
	Add Change Delete	INVESTIGATION/VIOLATION FORM (BOLDFACED ITEMS ARE REQUIRED)	DISTRIBUTION: Blue - Region/Local Program Canary - Data Entry Region Pink - Investigator/Data Entry
1	Primary Investigator Juriscode Site Name/Location: 906	Account Name: Hercules (MY) 08 09 89 Off Hours (Y) of Permit(s):  070 Other Juriscode 1  Marlin   Free port  mmy Tarkson 409	Other Juriscode 1
2	Federal Program (Y or N): NSP  'Investigation Type COSY I  Comment Compl, INV. 1	(5A Related Previous Investigation S NESHAP Situation Number In-House Investigation (Y or N) N°11	(COMPLIANCE DIV. ONLY)
	* * * FOR RECORD	OING REVIEWS OF COMPANY-SUBMITTED REAL PROPERTY Date Report Received	
	Analysis Review Results (C,N,U	Permit(s):	Retest Required?
3	Endown Decamen (V on N). NCD	Related Previous Investigation NESHAP Situation Number In-House Investigation (Y or N)	ACTOMORET ANSCHOOL DITTE CONTEST.
4	Rule Violated 101.44  Fill in the Following Applia Permit Number  Board Order Number  *FIN Involved  Violation Type  (C-Clerical Date NOV Sent (as MMDDYY) 29  Date NOV Received (as MMDDYY)	Permit Provision Court Order Number Facility Name (optional) N=Non-Clerical, I=Imminent Danger (DEFAULTS TO 5 DAYS A	E 14570
4	Violation Number 000 & CHAN Cause/Description Air Poll Rule Violated 4.01(a) To Fill in the Following Applia Permit Number Board Order Number ***FIN Involved	Ical  GES/DELETES ONLY) Situation Number  WHOM Problinited Contamode  CAH Contamode  Cable Items:  Permit Provision  Court Order Number  Facility Name (optional)  N=Non-Clerical, I=Imminent Danger  (DEFAULTS TO 5 DAYS AN	(COMPLIANCE DIV. ONLY)  OMPLIANCE DIV. ONLY)  - 14570  OFR Part
	**EPN REQUIRED FOR INVESTIGATION	INVESTIGATION TYPE CODES MATRIX N TYPES INDICATED ON BACK WITH AN * NS AS INDICATED WITH A + IN THE USER OUTH A . KNOTTS	R'S MANUAL RULE TABLE  Date: 8/23/89
	Approved By:		Date:
	Screen ID: IV1, IVI1, VL1	Page of Pages	ACB 93A (12/1/87) EEE OOO443

<u>Purpose</u>: This investigation was conducted in response to complaint No. 078900250 alleging nuisance dust from sandblasting and a choking chemical odor caused by Hercules Offshore, a neighboring barge cleaning and refurbishing operation. The complaint was received at approximately 2:10 p.m. on July 31, 1989.

<u>Investigative Findings</u>: At approximately 10:05 a.m. on August 9, 1989, Dwayne Meckler and I arrived in the vicinity of the complainant's residence and the Hercules Offshore facility. Sandblasting was being conducted on a barge at the Hercules facility (see attached photos). The dust was observed leaving the facility and traveling in a westerly direction towards the complainant's residence. The wind speed was 7 to 10 mph from a northeastly direction (45 degrees NE). A visit was made to the complainant's residence. At approximately 10:20 a.m. we arrived at the residence. The dust from the sandblasting made it extremely uncomfortable for both Dwayne and I to breath. Inside the complainant's house it was better. I spoke with the complainants (husband and wife). They stated that the sandblasting had been going on since the previous day, only on that day the blasting was being done on a barge that was located on the west side of the facility and closer to their residence. The complainant said that the dust was so bad that they had to leave home. They stated that at this time they could just stay inside with the windows closed. The wind was from the same northeasterly wind direction. The complainants stated that the neighboring facility had been causing problems for a number of years. The problems alleged were: dust from sandblasting and the venting off of the chemical barges containing vaporous compounds (such as benzene, styrene and other things). The complainants were concerned that with a new grandchild on the way (which they expect to be caring for) that there may be danger from breathing the pollution. They recounted an incident that occurred about a year ago where styrene fumes were vented during the night while everyone was sleeping with the windows open. The fumes filled the house and everyone woke up coughing and choking. The fumes were alleged to have killed a tree and other vegetation. facility was taken over by Hercules about a year and a half ago.

A change of ownership from Fish Engineering was submitted on January 25, 1989 and acknowledged by Lawrence Pewitt, Director, Permits Division Austin, on February 14, 1989 (letters in regional company file).

Upon leaving the complainant's residence a coat of fine dust (which was not there before we entered the residence) had accumulated on the state car. The dust again made it uncomfortable for us to breath. It was 11:30 a.m. and the sandblasting was still going on. The wind was still from the northeast.

A visit was made to the Hercules Offshore facility where we spoke with Jimmy Jackson, Craft Supervisor. Mr. Jackson was informed of the complaint against the facility. Mr. Jackson stated that the complaints from the neighbor (located to the west of the facility) were ongoing. He reported that the neighbor complains about everything from odors to the noise that a passing private boat makes. Mr. Jackson provided us with a tour of facility. At the middle of the facility on the south side there were four workers sandblasting a barge which created a tremendous amount of dust. I asked Mr. Jackson if that much sandblasting was the normal amount of activity. He stated that usually there are two workers but this job had to be finished sooner than anticipated. approximately 11:50 a.m. the sandblasting stopped apparently because it was lunchtime. The sandblasting was observed for one hour and 45 minutes. I asked Mr. Jackson if he could see that dust was being blown towards the houses located to the west of the plant, could be causing a problem. He answered I informed Mr. Jackson that we observed a significant amount of fine dust downwind of the sandblasting. This dust amounted to a nuisance and a violation of Board Rule 101.4 and compliance was requested.

The facility was built in the early 1950's. A TACB special exemption (Exemption X-3561) was issued 5/8/82 for a barge cleaning facility expansion by the previous owner, Fish Engineering, but due to economic conditions tankage increases did not occur and the expansion was not initiated except for the installation of a hot water heater. The sandblasting operation was grandfathered.

During the tour, moderate odors were observed near the barge cleaning and gas-freeing section of the plant. No odors were observed off plant property, however. There was a barge waiting to be cleaned which had been use to transport styrene. Mr. Jackson stated that they were waiting for the right wind direction to de-gas the barge. He said that they made the barges gas-free when the wind was blowing away from the residences. There were no means for controlling vapors from

BL-0118-V 8/9/89 Page 5

the barges. The only means of avoiding nuisance odor from the gas-freeing operation is noting the wind direction. Due to the high potential for nuisance associated with the gas-freeing operating of the barges, sampling is recommended when this activity is being conducted.

The complainants were informed of the investigative findings and recommendations regarding the complaint. They were also encouraged to contact the regional office should the conditions recur.

Conclusion: Hercules Offshore Company will be issued a Notice of Violation for Board Rule 101.4, which consisted of nuisance dust from the sandblasting of a barge. This dust was in such concentration and duration as to adversely affect the breathing and to interfere with the normal use and enjoyment of the property of residents downwind of the sandblasting. No enforcement action is recommended pending receipt and review of a requested written response from the company.

No nuisance odors were detected at the time of the investigation, however, due to the high potential for nuisance when the barge venting and gas-freeing operation is being conducted, sampling is recommended to assess health affects and/or hazards.

Mary A. Knotts

Environmental Quality Specialist

Region 7

Filename: 08896615.mak

Air Quality Control Region 7 5555 West Loop, Suite 300 Bellaire, Texas 77401 713/666-4964

The state of the s

· SEP 1 = 1989

现在最初的**的**现在,这一人的意思。

CERTIFIED MAIL (P 540 376 592) RETURN RECEIPT REQUESTED

1 6 6000 36

Mr. Mickey Tiner General Manager Hercules Offshore Company Post Office Drawer O Freeport, Texas 77541

> Re: Notice of Violation General Rule 101.4 Account No. BL-0118-V

Dear Mr. Tiner:

On August 9, 1989, Ms. Mary Knotts and Mr. Dwayne Meckler of this office observed a violation of Section 4.01(a) of the Texas Clean Air Act (Act) and Board General Rule 101.4, (copies enclosed) at your barge repair and cleaning facility located at 906 Marlin Street in Freeport, Brazoria County. The violation was noted from 10:05 a.m. to 11:50 a.m. and consisted of nuisance due to dust from the sandblasting of a barge. The dust was found in such concentration and such duration as to adversely affect the breathing and to interfere with the normal use and enjoyment of the property of residents downwind of the sandblasting. Verbal notification of the violation was given to Mr. Jimmy Jackson, Craft Supervisor, on the above investigation date and expedient compliance was requested.

The Act mandates specific enforcement actions with regard to violations of any provision of the Act, or any rule or order of the Board. These enforcement actions include the issuance

of a board order and Exposition of administrative penalties up to \$10,000 a day for each violation, or initiation of legal action for injunctive relief and/or civil penalties of \$50 to \$25,000 for each day and for each act of violation. In particular, the Act calls for mandatory compliance orders for nonclerical violations continuing thirty (30) days or more. The Board's enforcement obligations and alternatives are more fully explained in the enclosed "Enforcement Related Provisions of the Texas Clean Air Act".

Please notify this office of the circumstances relating to these violations and your plans for achieving prompt and continuous compliance. Your written response should be submitted within ten (10) days and should include a date by which continuous compliance will be achieved. The response should include the account number indicated in the reference line. If you have any questions with regard to this matter, please feel free to contact Ms. Knotts at this office.

Sincerely,

Original Signed By
Jenny Yang
Rerbert W. Williams, Jr.
Regional Director

Enclosures

cc: Kr. David Renrichs, Acting Director, Compliance Division, Austin

Mr. Leo D. O'Gorman, M.D., Director, Brazoria County Health Department, Angleton

bcc: RW/RR/MK/rsv, board was to be

Filename: 08896615.mak

Air Quality Control Region 7 5555 West Loop, Suite 300 Bellaire, Texas 77401 713/666-4964

ting the contracting the contracting the state of the contracting the contracting the contracting the contracting of

. SEP 1 = 1989

CERTIFIED MAIL (P 540 376 592) RETURN RECEIPT REQUESTED

Mr. Mickey Tiner General Manager bercules Offshore Company Post Office Drawer O Freeport, Texas 77541

> Re: Notice of Violation General Rule 101.4 Account No. BL-0118-V

Dear Mr. Tiner:

On August 9, 1989, Ms. Mary Knotts and Mr. Dwayne Meckler of this office observed a violation of Section 4.01(a) of the Texas Clean Air Act (Act) and Board General Rule 101.4, (copies enclosed) at your barge repair and cleaning facility located at 906 Marlin Street in Freeport, Brazoria County. The violation was noted from 10:05 a.m. to 11:50 a.m. and consisted of nuisance due to dust from the sandblasting of a barge. The dust was found in such concentration and such duration as to adversely affect the breathing and to interfere with the normal use and enjoyment of the property of residents downwind of the sandblasting. Verbal notification of the violation was given to Mr. Jimmy Jackson, Craft Supervisor, on the above investigation date and expedient compliance was requested.

The Act mandates specific enforcement actions with regard to violations of any provision of the Act, or any rule or order of the Board. These enforcement actions include the issuance

of a board order and imposition of administrative penalties up to \$10,000 a day for each violation, or initiation of legal action for injunctive relief and/or civil penalties of \$50 to \$25,000 for each day and for each act of violation. In particular, the Act calls for mandatory compliance orders for monclerical violations continuing thirty (30) days or more. The Board's enforcement obligations and alternatives are more fully explained in the enclosed "Inforcement Related Frovisions of the Texas Clean Air Act".

flease notify this office of the circusstances relating to these violations and your plans for achieving prompt and continuous compliance. Your written response should be submitted within ten (10) days and should include a date by which continuous compliance will be achieved. The response should include the account number indicated in the reference line. If you have any questions with regard to this patter, please feel free to contact Ms. Rnotts at this office.

Sincerely,

Original Signed By
Jenny Yang
Herbert W. Williams, Sr.
Regional Director

Inclosures

cc: Kr. David Benrichs, Acting Director, Compliance Division, Austin

Mr. Leo D. O'Gorman, M.D., Director, Brazoria County Health Department, Angleton

bec: RW/RH/MK/rsv,board.kide-

Filename: 08896615.mak

Air Quality Control Region 7 5555 West Loop, Suite 300 Bellaire, Texas 77401 713/666-4964

SEP 1 > 1989

CERTIFIED MAIL (P 540 376 592) RETURN RECEIPT REQUESTED

Mr. Mickey Tiner General Manager Hercules Offshore Company Post Office Drawer O Freeport, Texas 77541

> Re: Notice of Violation General Rule 101.4 Account No. BL-0118-V

Dear Mr. Tiner:

On August 9, 1989, Ms. Mary Knotts and Mr. Dwayne Meckler of this office observed a violation of Section 4.01(a) of the Texas Clean Air Act (Act) and Board General Rule 101.4, (copies enclosed) at your barge repair and cleaning facility located at 906 Marlin Street in Freeport, Brazoria County. The violation was noted from 10:05 a.m. to 11:50 a.m. and consisted of nuisance due to dust from the sandblasting of a barge. The dust was found in such concentration and such duration as to adversely affect the breathing and to interfere with the normal use and enjoyment of the property of residents downwind of the sandblasting. Verbal notification of the violation was given to Mr. Jimmy Jackson, Craft Supervisor, on the above investigation date and expedient compliance was requested.

The Act mandates specific enforcement actions with regard to violations of any provision of the Act, or any rule or order of the Board. These enforcement actions include the issuance

of a board order and imposition of administrative penalties up to \$10,000 a day for each violation, or initiation of legal action for injunctive relief and/or civil penalties of \$50 to \$25,000 for each day and for each act of violation. In particular, the Act calls for mandatory compliance orders for nonclerical violations continuing thirty (30) days or more. The Board's enforcement obligations and alternatives are more fully explained in the enclosed "Enforcement Related Provisions of the Texas Clean Air Act".

Please notify this office of the circumstances relating to these violations and your plans for achieving prompt and continuous compliance. Your written response should be submitted within ten (10) days and should include a date by which continuous compliance will be achieved. The response should include the account number indicated in the reference line. If you have any questions with regard to this matter, please feel free to contact Ms. Knotts at this office.

Sincerely,

Original Signed By
Jenny Yang
Herbert W. Williams, Jr.
Regional Director

Enclosures

cc: Kr. David Benrichs, Acting Director, Compliance Division, Austin

Mr. Leo D. O'Gorman, M.D., Director, Brazoria County Health Department, Angleton

bcc: RW/RR/MK/rsv.board.fd.

Filename: 08896615.mak

Twhere # 16-8

GroupIII

R

Bob Casale Rt. 3 - 135 Snapper Lane Freeport, Texas 77541

Octomber 5, 1989

Hercules Ceneral Manager Rt.3 - 904 Marlin Lane Freeport, Texas 77541

Dear Sir:

For the past year that your company has been in business at the Freeport location adjacent to Bridge Harbor Subdivision, we have had major problems with your operation. As you know prior to your business being operated at that location we have had similar problems with the previous owners.

In the past and recently we have informed you of several issues which are damaging to our health and property.

First issue being the opening of chemical barges: I have been informed by the Texas Air Control Board and the EPA as to the hazardous materials your operation handles. In the past there has been times that our house and the subdivision were filled with the odor of styrene and benezene gas.

As you know it is un-lawful to open chemical hatches in the intercoastal water-way. We are concerned why your company would continue to operate in such a close proximity to residence.

Our second concern is your sand blasting operation. We have called you numerous times complaining about the over spray of the sand blasting entering our house and causing damage to our house and automobilies. I understand that the Texas Air Control Board sited you recently for that problem; but to no avail you continue your damaging practice.

Our third concern is the banging of barges all hours of the day and night. Your operation is a seven day a week; twenty four hours a day nuisance. Each time we call you about the noise, you increase the noise to annoy us even more.

Our fourth concern is the out-door loud speaker that you operate. We have called your attention to this many times and you continue to operate so that it's heard through-out the subdivision.

As you know at the time of our complaints we have called the Community Awareness and Emergency Response organization and called Mr. Jim Overman with Dow Chemical who investigated several complaints. Showing concern I was told by Mr. Overman that at

one time Dow refused sending you barges because of your mishandling. I was also told by BASF Corporation that they do not so send barges to your business because of mishandling.

We have experience sick conditions such as watery eyes, tightness of the chest, headaches and nasal congestion. At one time the chemicals from your operation killed all the leaves from the trees on the east side, through-out the whole subdivision.

We are informing your organization that we are holding you responsible and liable for any and all damages including health and property to us and demand that your operation cease to allow chemical gases and over spray of sand blasting to affect our home environment.

We trust that you take this matter into very critical consideration.

Thank You Casale
Bob and Stella Casale

cc;
Air Control Board
City of Freeport
U.S. Coast Guard - Galveston
EPA - Dallas
Tom Delay U.S. Representative
J.E. "Buster" Brown - State Senator
John Willy State Representative
State Attorney General

Residence of Bridge Harbor Subdivision: Letter dated Octomber 5, 1989

JEFF FOURRIER 66 MARCIN FREEPORT TX 77541 233-3605

DENNIS + JOANN HENERER
RT 2 BOXIITC
BAYC.+4 TI 77414
116 REDF.SK
FREEPORT TX 77541

B.K. Schopins:
Denesa Schopins
P.O. Box 3010-A
118 Bellich line
Theopolie, TX 171541

Ruth Bus by
Rt.3.63 marlin
Freepont, tx 77541
A73-4817

Betty Lewis

RH#3 Box 61 Martin

Free Bort Tr. 77541

233.0288

Julic Chroworth

92 Dolpnin in

Freeport, Tr. 77541

409-2337935

Jamh 9 Darathy furung

101 Dalphin Jane

J. reeport Floor 44107

Bos J. ARMSTRONG

38 TARRON LANE

265-5432

DANNY MANCHES

MANLIN LANE (SHIMP BOAT)

233-3966 (MISSINENE)

BEN SCHNAPP

82 POLPHIN, LU,

233-3416 -

Mike Momsen &7 Dolphin Ln. Rt.3 Freeport, Tex. 77541 409-233-7227 Bob Casale Rt. 3 - 135 Snapper Lane Freeport, Texas 77541

Octomber 5, 1989

Hercules Ceneral Manager Rt.3 - 904 Marlin Lane Freeport, Texas 77541

Dear Siri

For the past year that your company has been in business at the Freeport location adjacent to Bridge Harbor Subdivision, we have had major problems with your operation. As you know prior to your business being operated at that location we have had similar problems with the previous owners.

In the past and recently we have informed you of several issues which are damaging to our health and property.

First issue being the opening of chemical barges: I have been informed by the Texas Air Control Board and the EPA as to the hazardous materials your operation handles. In the past there has been times that our house and the subdivision were filled with the odor of styrene and benezene gas.

As you know it is un-lawful to open chemical hatches in the intercoastal water-way. We are concerned why your company would continue to operate in such a close proximity to residence.

Our second concern is your sand blasting operation. We have called you numerous times complaining about the over spray of the sand blasting entering our house and causing damage to our house and automobilies. I understand that the Texas Air Control Board sited you recently for that problem; but to no avail you continue your damaging practice.

Our third concern is the banging of barges all hours of the day and night. Your operation is a seven day a week; twenty four hours a day nuisance. Each time we call you about the noise, you increase the noise to annoy us even more.

Our fourth concern is the out-door loud speaker that you operate. We have called your attention to this many times and you continue to operate so that it's heard through-out the subdivision.

As you know at the time of our complaints we have called the Community Awareness and Emergency Response organization and called Mr. Jim Overman with Dow Chemical who investigated several complaints. Showing concern I was told by Mr. Overman that at

· 其一名名人名 和上的方式工作人名 在下的人名 人名英格兰斯特人 的复数人名 我们就是我们的人的人,我们就是一个人的人,我们们就是一个人的人,我们们就是一个人的人,我们们们们们们的人们们们们们们们们

one time Dow refused sending you barges because of your mishandling. I was also told by BASF Corporation that they do not se send barges to your business because of mis-handling.

We have experience sick conditions such as watery eyes, tightness of the chest, headaches and nasal congestion. At one time the chemicals from your operation killed all the leaves from the trees on the east side, through-out the whole subdivision.

We are informing your organization that we are holding you responsible and liable for any and all damages including health and property to us and demand that your operation cease to allow chemical gases and over spray of sand blasting to affect our home environment.

We trust that you take this matter into very critical consideration.

Thank You. Casale Bob and Stella Casale

cc:
Air Control Board
City of Freeport
U.S. Coast Guard - Galveston
EPA - Dallas
Tom Delay U.S. Representative
J.E. "Buster" Brown - State Senator
John Willy State Representative
State Attorney General

#### Residence of Bridge Harbor Subdivision: Letter dated Octomber 5, 1989

JEFF FOURRIER 66 MARCIN FREE PORT TX 77541 233-3605

DENNIS + SOANN HENERE RT & BOXIITC Bay C. + 4 To 77414 116 REDFISH FREEDRIT TX 77541

R.K. Schapins:
Dinion Schapins
Discoverion
Historial Line
Heepon E. T. 17841

Ruth Bus by
R1.3 63 marlin
Freepent, +x 77541
233-4817

Horty Lewis

13 Box 61 Martin

Coengort Fr. 77 541

253 Cassi

Julie Chrosworth

42 Dolphin in

Treeport The 77341

418-233 7935

Jamp & Darathy firming

Jet Dalphin Jane

Treeport Flant ANIOT

Desi J. ARPON LANE

38 TARPON LANE

365-5432

DANNY MANCHES

MANLING LANG (SHEAR POAT)

033-3966 (MISSINENE)

BEN SCHNAPP

82 POLPHIN, LN,

233-3416 -

Mike Momsen B7 Dolphin Ln. Rt.3 Freeport, Tex. 77541 409-233-7227

ALENSE COMPLETE THE POL	LEUWING INFORMATION:
Your name Bol3	CASALE
Representing	
Address 13T S	NAPPER LM.
FREE	
Company name	SEUF.
Permit number <u>χ 356/</u>	OR Compliance account no. <u>BL0118</u> V
Assisted by	Region 7
Date 10/9/89	, negron ,
vale	- <del></del>

PLEASE COMPLETE THE FOLL	OWING INFORMATION:
Your name Bol3	CASALE
Representing	
Address 13T SN	APPER LM.
FLEEPO	•
Company name	SEUF.
Permit number <u>x 3561</u>	OR Compliance account no. <u>BL0118</u> V
	. 0.17
Assisted by	Region 7
Date 10/9/89	<u> </u>

PLEASE COMPLETE THE FOLLOWING INFORMATION: Your name Harry M, Walks		
Representing 14, M. Walter & Assoc Que  Address 3321: E. Bayon Dr.		
Company name / firely Offshire	<u>.</u>	
Permit number $\times -356/$ OR Compliance account	no	<u> </u>
	•	serion 7
Assisted by	1	Region 7

PLEASE COMPLETE THE FOLL	OWING INFORMATION	l:	
Your name DAUID D	BUNARS	<u> </u>	est, in the desired specification of
Representing P. C. of	Associator		<del></del>
Address 2707 N	Loop West	Suite 400	<u></u>
Company name Hercules  Permit number Usins	OffsHore OR Compliance	account no.	BL-0118-1
Assisted by		1	Region 7
Date	<del></del> .		

Bob Casale Rt: 3 - 135 Snapper Lane Freeport, Texas 77541

October 10, 1989

City of Freeport Administration 128 East 4th Street Freeport, Texas 77541

Dear Sirsi

We are bringing a continuous problem to your attention which we have complained about for several years.

The subject matter is the operation of Fish Engineering and Hercules Off-Shore Drilling Company.

We have enclosed a letter dated October 5. 1989 to that Company.

In general our complaints have been the exposure to dangerous chemicals, exposure to sand-blasting materials, and the loud abusive noises.

Each time we have complainted to the city manager, the health department, members of city council, also to Mayor Alan Faulk and past Mayor Mark Vanderveer we have received no response to curtail the operation or safe-guard the health and safety of the adjacent residences.

As the October 5, 1989 letter indicates the present Company is engaged in the barge cleaning process. There is one case in particular that the residents were heavily exposed to benezene gas. I called the city manager and asked if he would send the health officer to investigate the matter. Two hours had pasted and no-one appeared from the city to investigate. I then called back and the operator told me everyone had gone to lunch; apparently lunch is more important to the city than to go out and investigate persons who are being exposed to dangerour gases. Finally about three days later a city health officer and a member of the Texas Air Control Board came to the scene. At that point we had a lengthy discussion as to the problems we are having with these companies. At that time we again showed pictures of the leaves of the trees that had died due to chemical releases.

Dangerous chemicals are extracted from the barges and vents are being opened exposing residents to gas releases. There has been several incidents where the barges are brought in at night and the hatches are being opened durning the time that the residents are sleeping; making us un-aware of the danger until morning.

The continuous sand-blasting which sometimes starts a 7:30 a.m. till dark has caused us many problems. We are unable to open our windows: our automobilies have been damaged and covered with the over-apray. Our downstairs patio is also always filled with

particles of the sand-blasting. When we attempt to breath outdoors our lungs, throat, eyes and nose are filled with the particles. As we write this letter at 6:00 p.m. the sand-blasting is taking place. A cloud of dust can be visually seemed. We are unable to open windows, the high pressure screeching sound from the sand-blasting can be heard from the furtherest room in our home.

About a month ago I requested that Mayor Alan Faulk meet me at my house to investigate this matter. When he visited, I showed him the close proximity of this business to our residences. He agreed that we do have a problem. I then showed him our downstairs patio; and asked him to rub his hand over the thick debris on a table top which was filled with over-spray from the business. I then asked him to investigate this matter further; as to what remedies can be taken to curtail and cease the annoying and dangerous process.

されているとのです。 一般 日本 などのないにないないない Three days past without word from Mayor Alan Faulk. I called him: to ask if he had finish his investigation. He responded that he had finish his investigation. He responded that he had talked to the city manager and city attorney and they said nothing could be done by the city because the city re-zoned the land to conduct > that type of business. I told him, in the future, I wish to add on to my house, he said "quote" that you "Bob Casale" should straighten out that problem "being Hercules" before you add on to your house. He also told me that I should call Marvin Zindler from T.V. channel 13 in Houston; to have him investigate; maybe he could do something.

If I ever experienced deraliction of duty, from a governmental official this is a prime example.

We have also mentioned about the loud abusive noise. Many times durning the operational phase of this business they bang on barges and the sounds are heard through-out the subdivision.

The recorded facts relate that the business location has caused these problems for many years.

On April 17,1989 the city of Freeport held a city council and planning commission public hearing to re-zone several parcels of land in and around the Bridge Harbor Subdivision, including the business in question. After hearing from approximately thirty persons opposing this zone change, the city ignored the complaints and went on to re-zone the land from light manufacturing to water-front heavy. This action to us was pure irresponsiable and deliberate unconcern for the health and safety for near-by residence; knowing the dangerous consequence and nuisance that this change made.

Several times officals with the Texas Air Control Board told me that I should call the city of freeport so that they could make an immediate investigation. I was told by city officals that the city did not have a qualified person to investigate.

As of this date we are requesting that the city of Freeport contact the County Health Department for assistance. I have had several discussions with County Judge John Damon and he stated that their office would assist if requested by the City of Freeport.

About 12:45 p.m. October 11, 1989 I met Robby Blair on the corner of Snapper and Marlin Lane. He told me that he was investigating that mornings complaint. I showed him the over-spray blowing over the city street and pointed out the loud blasting noise. I also told him that he should talk to the shrimper Danny Marches working about two hundred feet from us. and adjacent to the barge being sand-blasted. He refused to go. I then went to Danny Marches and told him what had happen.

In summary we wish to inform, that city officals, have a moral and legal responsibility to the people and have a duty to safe-guard the safety and welfare of the citizens.

As of this date we find no documentation where the city of freeport has made any attempt to safe-guard and protect the citizens in this case.

We here-by notify the city officals, who were resposiable for the damaging zone changes and allowing the problems to occur past and present; that we are holding them resposiable for damanges to health and property in this case.

In trust, we hope the city officals who are in-powered to act, and according to law; to safe-guard the citizens in this case, and act with deligence.

Thank You. Pasale Stella Casale Bob and Stella Casale

CCI

Mayor Alan Faulk
Councilman:
Jim Phillips
Milan Miller
John Stanford
Horace Owings
Brazoria County Health Department

Texas Air Control Board
EPA
Jim Mattox - Texas Attorney Genera
J.E. "Buster" Brown - State Senato
John Willy - State Representative
Tom Delay - U.S. Representative

The second secon

· Di



# 128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / [409] 233-3526

	Pate Received 10-13-8
	Time Received 9:00
. VIOLATION INFORMATION	
Date: 10-13.99 Time: 9.00	
Nature of Violation:	
See Attached Steet.	Satel Oct 5, 1981 SHeet
By Relly 2 36:	
LOCATION	X OWNER OF BUSINESS/PROPERTY
Name: Hercules	Name: Hercules
Address: Bt. 3 904 Markin Land	Address: Ot 3 904 Markin Lan
Phone:	Phone: Kegport Tayns 27541
. *******	*******
COMPLAINTANT INFORMATION	
Name: Bob CAsola	Business Name: Same As Co-pl
Address: Rs #3	Business Address:
Phone: Freignt Tayer 1754/	Phone:
	1 Best and
	Signature of Complaintant
*****	********
INVESTIGATION OF COMPLAINT	
Date: 10-13-91 Time: 9.06	
Investigation Revealed:	·
<del></del>	T&E000063



#### 128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / (409) 233-3526 .

	vate kecewea. 10-13-31
	Time Received 9:45 Am
VIOLATION INFORMATION	
Date: 10-13-89 Time: 9:45 Any	•
Nature of Violation:	
	then) dated Oct. 5, 1989 Sheet
Received by, Bobby Blair	
name of many	
LOCATION	OWNER OF BUSINESS/PROPERTY
Name: Hercules	Name: flercules
Address: Rt 3 904 Marlin Lane	Address: Rt 3 704 Marlin Lane
Phone:	Phone: Freeport, TK 77541
****	
COMPLAINTANT INFORMATION	•
Name: B. K. Schoggino	Business Name: some as complaint
Address: 118 Kerful The	Business Address:
Phone: Frepst to 17541	Phone:
•	× BSI Schoggin
	Signature of Complaintant
****	****
INVESTIGATION OF COMPLAINT	
Date: 10-13-89 Time: 9:45 A.M.	
Investigation Revealed:	
	· · · · · · · · · · · · · · · · · · ·
· · · · · · · · · · · · · · · · · · ·	Vigil (b) (ro)
	T&E 000064



## 128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / [409] 233-3526

	Date Received 10-13.89
	Time Received 10:00 ma
VIOLATION INFORMATION	
Date: 10-13-89 Time: 10:00 AN.	
Nature of Violation:	
See attacked Sheet (	etter) dated Oct 5 1989 - Sheet
Received to Babby Blair	
LOCATION	OWNER OF BUSINESS/PROPERTY
Name: Hercules	Name: Hercules
Address: Ct 3 904 Marlin Lone	Address: Rf 3 904 Marlin Line
Phone: Regort To 2754	Phone: Freeport TX 775K1
****	************
COMPLAINTANT INFORMATION .	
Name: Oulie Sonsworth	Business Name: Same as Comple
Address: 92 Dolphy In	Business Address:
Phone: 2331975	Phone:
	$(a,b)^{-1}$
	Sinter of Containing
	Signature of Complaintant
***	********
INVESTIGATION OF COMPLAINT	
Date: 10-13-89 Time: 10:00 Ang.	
Investigation Revealed:	

Mr. B.K. Schoggin 118 Redfish Lane Freeport, TX 77541

Part of the second

On October 11, 1989, at 9:45 a.m. Freeport Code Compliance Inspector and the Brazoria County Health Inspector and I visited Mr. and Mrs. B.K. Schoggins at their home. Mr. Schoggins signed a complaint against Hercules Offshore Orilling Company complaining of chemical odors that he notice occasionally when the winds blow out of the Northeast as he feels that they are coming from Hercules Offshore Orilling Company. Though he does not smell the odors all the time he was concerned about one particular Sunday in which he noticed the odor to be extremely offensive and was concerned of its chemical content and a repeated incidence. He wanted reassurance that the chemicals in the air were not harmful to him and his family.

We thanked Mr. and Mrs. Schoggin for their assistance and told them we would investigate further into their concerns.

Julie Ainsworth 92 Dolphin Lane Freeport, TX 77541



On October 11, 1989 at 10:00 a.m. Freeport Code Compliance Inspector and. the Brazoria County Health Inspector and myself visited Ms. Julie Ainsworth at her home. Ms. Ainsworth signed a complaint against Hercules Offshore Drilling Company at this time. She says she has been living at Bridge Harbor subdivision for the last three months and plans to stay until their house is sold. She stated she and her two children have not been feeling well the whole time. She claims to have allergies and one of the children has been to the doctor for a rash problem. The doctor has prescribed medication for the rash but offered no diagnosis as to what caused it. Ms. Ainsworth says she can not open her windows in the house because of the chemical odors that she believes comes from Hercules Offshore Drilling Company. She expresses her concern about the odors and thinks it might be affecting her allergies since she feels worse at her current location than where she used to live. The Brazoria County Health Inspector mentioned that due to the very dry weather in Brazoria County and being fall season be noticed that many residents throughout Brazoria were experiencing breathing problems related to allergies from ragweed and other related matter in the air. We asked if she received any doctors' reports relating the cause of her or her children's illness to any chemical exposure and she stated that no doctor has claimed any chemical-related illness at this time.

We thanked Ms. Ainsworth for her assistance with our report and went to Hercules Offshore Drilling Company to talk to the General Manager Mr. Tinner.

Mr. Tinner Hercules Offshore Drilling Company Freeport, TX 77541

When investigating Hercules Offshore Drilling Company at approximately 11:00 a.m. on October 11, 1989 we watched for signs of dead foliage along the roadway to the entrance of the business as well as outside of the fenced-in area at the location. We walked around the barge drydock facility where sandblasting operations are performed, which is directly behind a large mound of dirt where weeds and grass are growing. We did not see any signs of dead foliage nor experience eye-irritating fumes any time during our visit. Of the several barges at the site only one particular barge appeared to have odors but this could not be detected until one got close to the barge dry dock area.

We talked with General Manager Micky Tinner to assess Mr. Castle's complaints. He said he was aware of Mr. Casale's concerns and had taken measures to prevent discomforts that might be irritate area residents.

Mr. Tinner stated that policies had been implemented to prevent any sand from the sandblasting operations to drift onto properties toward the Bridge Harbor area when Mr. Casales's concerns were first raised. According to Mr. Tinner, Hercules Offshore Drilling's policy is to discontinue all operations when winds blow out of the Northeast toward Bridge Harbor. Mr. Tinner showed us the techniques used in measuring the distance and direction in which the sand moves during blasting operations. Mr. Tinner mentioned that it was very costly to shut his operations down when the winds blew out of the Northeast.

Mr. Tinner mentioned that his company was trying to eliminate concerns regarding sand coming from his business by erecting a 24 foot tall and 400 foot long tennis court-type fence made of plastic material around the sandblasting operation in such a way that it would create a wind tunnel and help direct air flow away from the direction of the Bridge Harbor subdivision. The fence materials are on order and the fence should be erected soon.

We asked Mr. Tinner about Mr. Casale's concerns of being exposed to dangerous chemicals at his residence, particularly the incident Mr. Casale refered to in his letter of October 10, 1989, where he states that "residents were heavily exposed to benezene gas." Mr. Tinner said that the barge Mr. Casale was concerned about had unloaded the chemical Benezene in Houston and its tanks flushed before arriving at his facility. According to Mr. Tinner the only reason Mr. Casale knew that the barge had contained Benzene products was because he had read warning signs on the side of the barge with his binoculars as he often does.

Mr. Tinner stated that before work was done on any barges brought to his facility they must be inspected and certified before his men can go inside to do any hot work or cleaning. Certified equipment (air detectors) must

軍基最000068

be used to perform such inspections and are necessary to get the certification that is required of Hercules Offshore Drilling. We were shown original documents of certificates where permission was received to begin work on barges. We were told that all the certificates and records were kept on file at all times to show what barges are brought on the premises.

Mr. Tanner mentioned that precautions are taken to insure the safety of his employees as well as the community. He said that they semetimes have up to forty five men working in and around the barges on a daily basis.

Mr. Tinner said that he has talked to the Texas Air Control Board in the past and that they have been to his business to monitor the quality of air in the surrounding area. (I personally have not seen the Texas Air Control Board's findings at this time).

We asked Mr. Tinner about Mr. Casale's noise complaint and he stated that a majority of the noise Mr. Casale complains of comes during the very late or early hours of the morning. Mr. Tinner said his men work occasional overtime until 7:00 or 8:00 p.m. at night but their usual work hours are from 7:30 a.m. to 3:30 p.m. They do work overtime on some weekends if they have to get a barge contract completed. We discussed with Mr. Tanner the City's noise ordnances restricting loud noises from 11:00 p.m until 7:00 a.m Sunday through Saturday and from 11:00 p.m Saturday through Sunday afternoon until 1:00 p.m and told him that we expected the ordinances would continue to be observed.

DATE: 10-10-88

TO: Robby Blair, Meryl Walters and Earl Heath

FROM: Jo-Ann Proctor

Re: Nuisance odor at Bridge Harbor

An investigation of Mr. Casale's complaint revealed no odor, no eye irritating fumes and no dead foliage. In investigating Fish Engineering, I discovered the work performed there was heavily regulated and all procedures were well documented. Mr. Tom Randolph, the Fabrication/Marine Manager was very cooperative in showing me the entire dock facility and explaining what type of work took place there. He also explained the precautions taken regarding safety and steps to not inconvenience Mr. Casale. He supplied me with safety reports to read from numerous local, State and Federal agencies. He also gave me a copy of one of their Marine Chemist Certificates (see attached) which is issued prior to work being done on each barge. He explained he had experienced many complaints from Mr. Casale and Fish Engineering had gone to great lengths to alleviate Mr. Casale's fears. When he complained of a bad odor, Fish added a cherry-vanilla fragrance but Mr. Casale continued to complain on the basis of in his opinion, any chemical which had an odor was toxic.

Since Mr. Randolph is well aware of Mr. Casale's presence, it is policy not to open barge tanks which might release obnoxious of toxic fumes when the win is blowing from the North-East which could possibly carry the fumes over Mr. Casale's property. According to Mr. Randolph's records there had been no tanks opened on the date and time which Mr. Casale was complaining. Furthermore, Jim Mueth of the U.S. Coast Guard/Marine Safety Division, had been present on the Fish Engineering dock from approximately 10:40 AM until 4:00 PM on October 7, 1988 and had not noted any odor. Mr. Randolph did not feel his dock had been the source of any nuisance odors or toxic rumes that date.

Today I received a call from Paul Hunt with the Texas Air Control Board. He will be in my office tomorrow morning. He would like for me to accompany him on an investigation of Mr. Casale's complaint. I would appreciate any further instructions you may have.

Sincerely.

Jo-Ann Proctor, Health Inspector

JAP:saa



128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / (409) 233-3526

October 16, 1989

In summary to this preliminary report I have spoken to Ms. Mary Knotts of the Compliance Section of the Texas Air Control Board on the 16th of October 1989, to request that I accompany her on investagation of Mr. Casale's complaint. She is scheduled to arrive in Freeport Tuesday October 17, 1989.

As of this date there are two complaint reports at Bridge Harbor; one dated October 10, 1989 and one dated October 13, 1989. A complete report will follow after above inspection with Air Control Inspector.

Sincerely

Robby L. Blair Building Official City of Freeport

RLB:sd



128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / [409] 233-3526 .

#### COMPLAINT FORM

	Date Received 10-13-8
	Time Received 9.00
/IOLATION INFORMATION	
Date: 10-13.99 Time: 9.00	
Nature of Violation:	
See Artaches Steet.	Satel Oct 5, 1987, SHeat,
By Relly 2 St.	
	·
LOCATION	X OWNER OF BUSINESS/PROPERTY
Name: Herches	Name: Hexc-les
Address: Rt. 3 904 Marlin Lone	Address: 123 904 Marlin Lan
Phone:	Phone: Keepert 1415 27541
****	*******
COMPLAINTANT INFORMATION	
Name: Bah CAsale	Business Name: Same As Corpo
Address: 1 # 3	Business Address:
Phone: Therport Tayor 1754/	Phone:
- Company of the state of the s	
	RM
	X I was a
	Signature of Complaintant
M 44 44 11 24 11 11	*******
******	
INVESTIGATION OF COMPLAINT	
· · · · · · · · · · · · · · · · · · ·	
Date: 10-11-07 Time: 9.06	
· · · · · · · · · · · · · · · · · · ·	

不為層 000154



#### 128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / (409) 233-3526 .

		rate Receiveu.	10-15-01
	* + <sub>n*</sub>	Time Received_	9:45 AM
VIOLATION INFORMATION			
Date: 10-13-89 Time: 9:45 Any		•	
Nature of Violation:	· · · · · · · · · · · · · · · · · · ·		
See attacked Sheet (	letter) detel Oc	1. 5. 1989	Seet
Received by Babbie Blair	·		
γ. θ.			
LOCATION	OWNER OF BUSIN	ESS/PROPERTY	
Name: Hercules	Name: <u>fle</u>	cules	
Address: Rt 3 904 Marlin Lane		3 704 Mar	lin Lane
Phone:	Phone: Tre	pod, Tx 77	541
****	******	•	•
•			
COMPLAINTANT INFORMATION			
Name: B. K. Schoggino		some as	complaint
Address: 118 Redfiel Line	Business Addre	2.5.5:	
Phone: Truppet, to 17541	Phone:	·	
•	2011	2	
	× BSI Del	oggin	· · · · · · · · · · · · · · · · · · ·
	Signature of (	Complaintant	
***	********		
INVESTIGATION OF COMPLAINT			
Date: 10-13-89 Time: 9:45 A.M.			
Investigation Revealed:		<del></del>	
	· · · · · · · · · · · · · · · · · · ·	· ·	
	·	<del></del>	



128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / (409) 233-3526

	Date Received 10-13.89
	Time Received 10:00 mm.
VIOLATION INFORMATION	
Date: 10.13-89 Time: 10:00 A.M.	
Nature of Violation:	
See attacked Sheet ( &	then) dated Oct 5 189 - Sheet
Received by Baby Blair	
	· · · · · · · · · · · · · · · · · · ·
LOCATION	OWNER OF BUSINESS/PROPERTY
Name: Hercules	Name: <u>Hercules</u>
Address: Et 3 904 Marlin Line	Address: Rt 3 904 Marlin Lane
Phone: Report Tx 7754	Phone: Fleeport Tx 77541
<b>,</b> ,	
****	************
COMPLAINTANT INFORMATION .	
Name: Quelic Sinswort	Business Name: Same as Complini
Address: 92 Dalopus An	Business Address:
Phone: 2337975	Phone:
	0.0.
	Y Allily Junesonsh
	Signature of Complaintant
***	**********
INVESTIGATION OF COMPLAINT	
Date: 10-13-89 Time: 10:00 Ang.	
Investigation Revealed:	

Mr. B.K. Schoggin 118 Redfish Lane Freeport, TX 77541

On October 11, 1989, at 9:45 a.m. Freeport Code Compliance Inspector and the Brazoria County Health Inspector and I visited Mr. and Mrs.-B.K. Schoggins at their home. Mr. Schoggins signed a complaint against Hercules Offshore Drilling Company complaining of chemical odors that he notice occasionally when the winds blow out of the Northeast as he feels that they are coming from Hercules Offshore Drilling Company. Though he does not smell the odors all the time he was concerned about one particular Sunday in which he noticed the odor to be extremely offensive and was concerned of its chemical content and a repeated incidence. He wanted reassurance that the chemicals in the air were not harmful to him and his family.

We thanked Mr. and Mrs. Schoggin for their assistance and told them we would investigate further into their concerns.

Julie Ainsworth 92 Dolphin Lane Freeport, TX 77541



On October 11, 1989 at 10:00 a.m. Freeport Code Compliance Inspector and, the Brazoria County Health Inspector and myself visited Ms. Julie Ainsworth at her home. Ms. Ainsworth signed a complaint against Hercules Offshore Drilling Company at this time. She says she has been living at Bridge Harbor subdivision for the last three months and plans to stay until their house is sold. She stated she and her two children have not been feeling well the whole time. She claims to have allergies and one of the children has been to the doctor for a rash problem. The doctor has prescribed medication for the rash but offered no diagnosis as to what caused it. Ms. Ainsworth says she can not open her windows in the house because of the chemical odors that she believes comes from Hercules Offshore Drilling Company. She expresses her concern about the odors and thinks it might be affecting her allergies since she feels worse at her current location than where she used to live. The Brazoria County Health Inspector mentioned that due to the very dry weather in Brazoria County and being. fall season be noticed that many residents throughout Brazoria were experiencing breathing problems related to allergies from ragweed and other related matter in the air. We asked if she received any doctors' reports relating the cause of her or her children's illness to any chemical exposure and she stated that no doctor has claimed any chemical-related illness at this time. .

We thanked Ms. Ainsworth for her assistance with our report and went to Hercules Offshore Drilling Company to talk to the General Manager Mr. Tinner.

Mr. Tinner Hercules Offshore Drilling Company Freeport, TX 77541

When investigating Hercules Offshore Drilling Company at approximately 11:00 a.m. on October 11, 1989 we watched for signs of dead foliage along the roadway to the entrance of the business as well as outside of the fenced-in area at the location. We walked around the barge drydock facility where sandblasting operations are performed, which is directly behind a large mound of dirt where weeds and grass are growing. We did not see any signs of dead foliage nor experience eye-irritating fumes any time during our visit. Of the several barges at the site only one particular barge appeared to have odors but this could not be detected until one got close to the barge dry dock area.

We talked with General Manager Micky Tinner to assess Mr. Castle's complaints. He said he was aware of Mr. Casale's concerns and had taken measures to prevent discomforts that might be irritate area residents.

Mr. Tinner stated that policies had been implemented to prevent any sand from the sandblasting operations to drift onto properties toward the Bridge Harbor area when Mr. Casales's concerns were first raised. According to Mr. Tinner, Hercules Offshore Drilling's policy is to discontinue all operations when winds blow out of the Northeast toward Bridge Harbor. Mr. Tinner showed us the techniques used in measuring the distance and direction in which the sand moves during blasting operations. Mr. Tinner mentioned that it was very costly to shut his operations down when the winds blew out of the Northeast.

Mr. Tinner mentioned that his company was trying to eliminate concerns regarding sand coming from his business by erecting a 24 foot tall and 400 foot long tennis court-type fence made of plastic material around the sandblasting operation in such a way that it would create a wind tunnel and help direct air flow away from the direction of the Bridge Harbor subdivision. The fence materials are on order and the fence should be erected soon.

We asked Mr. Tinner about Mr. Casale's concerns of being exposed to dangerous chemicals at his residence, particularly the incident Mr. Casale refered to in his letter of October 10, 1989, where he states that "residents were heavily exposed to benezene gas." Mr. Tinner said that the barge Mr. Casale was concerned about had unloaded the chemical Benezene in Houston and its tanks flushed before arriving at his facility. According to Mr. Tinner the only reason Mr. Casale knew that the barge had contained Benzene products was because he had read warning signs on the side of the barge with his binoculars as he often does.

Mr. Tinner stated that before work was done on any barges brought to his facility they must be inspected and certified before his men can go inside to do any hot work or cleaning. Certified equipment (air detectors) must

be used to perform such inspections and are necessary to get the certification that is required of Hercules Offshore Drilling. We were shown original documents of certificates where permission was received to begin work on barges. We were told that all the certificates and records were kept on file at all times to show what barges are brought on the premises.

Mr. Tanner mentioned that precautions are taken to insure the safety of his employees as well as the community. He said that they sometimes have up to forty five men working in and around the barges on a daily basis.

Mr. Tinner said that he has talked to the Texas Air Control Board in the past and that they have been to his business to monitor the quality of air in the surrounding area. (I personally have not seen the Texas Air Control Board's findings at this time).

We asked Mr. Tinner about Mr. Casale's noise complaint and he stated that a majority of the noise Mr. Casale complains of comes during the very late or early hours of the morning. Mr. Tinner said his men work occasional overtime until 7:00 or 8:00 p.m. at night but their usual work hours are from 7:30 a.m. to 3:30 p.m. They do work overtime on some weekends if they have to get a barge contract completed. We discussed with Mr. Tanner the City's noise ordnances restricting loud noises from 11:00 p.m until 7:00 a.m Sunday through Saturday and from 11:00 p.m Saturday through Sunday afternoon until 1:00 p.m and told him that we expected the ordinances would continue to be observed.

DATE: 10-10-88

TO: Robby Blair, Meryl Walters and Earl Heath

FROM: Jo-Ann Proctor

Re: Nuisance odor at Bridge Harbor

An investigation of Mr. Casale's complaint revealed no odor, no eye irritating fumes and no dead foliage. In investigating Fish Engineering, I discovered the work performed there was heavily regulated and all procedures were well documented. Mr. Tom Randolph, the Fabrication/Marine Manager was very cooperative in showing me the entire dock facility and explaining what type of work took place there. He also explained the precautions taken regarding safety and steps to not inconvenience Mr. Casale. He supplied me with safety reports to read from numerous local, State and Federal agencies. He also gave me a copy of one of their Marine Chemist Certificates (see attached) which is issued prior to work being done on each barge. He explained he had experienced many complaints from Mr. Casale and Fish Engineering had gone to great lengths to alleviate Mr. Casale's fears. When he complained of a bad odor, Fish added a cherry-vanilla fragrance but Mr. Casale continued to complain on the basis of in his opinion, any chemical which had an odor was toxic.

Since Mr. Randolph is well aware of Mr. Casale's presence, it is policy not to open barge tanks which might release obnoxious of toxic fumes when the wind is blowing from the North-East which could possibly carry the fumes over Mr. Casale's property. According to Mr. Randolph's records there had been no tanks opened on the date and time which Mr. Casale was complaining. Furthermore, Jim Mueth of the U.S. Coast Guard/Marine Safety Division, had been present on the Fish Engineering dock from approximately 10:40 AM until 4:00 PM on October 7, 1988 and had not noted any odor. Mr. Randolph did not feel his dock had been the source of any nuisance odors or toxic fumes that date.

Today I received a call from Paul Hunt with the Texas Air Control Board. He will be in my office tomorrow morning. He would like for me to accompany him on an investigation of Mr. Casale's complaint. I would appreciate any further instructions you may have.

Sincerely.

Jo-Ann Proctor, Health Inspector

JAP:saa

本作のとあるとは個別であ



128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / (409) 233-3526

October 16, 1989

In summary to this preliminary report I have spoken to Ms. Mary Knotts of the Compliance Section of the Texas Air Control Board on the 16th of October 1989, to request that I accompany her on investagation of Mr. Casale's complaint. She is scheduled to arrive in Freeport Tuesday October 17, 1989.

As of this date there are two complaint reports at Bridge Harbor; one dated October 10, 1989 and one dated October 13, 1989. A complete report will follow after above inspection with Air Control Inspector.

Sincerely

Robby L. Blair Building Official

City of Freeport

RLB:sd

Mr. Tinner Hercules Offshore Drilling Company Freeport, TX 77541

When investigating Hercules Offshore Drilling Company at approximately 11:00 a.m. on October 11, 1989 we watched for signs of dead foliage along the roadway to the entrance of the business as well as outside of the fenced-in area at the location. We walked around the barge drydock facility where sandblasting operations are performed, which is directly behind a large mound of dirt where weeds and grass are growing. We did not see any signs of dead foliage nor experience eye-irritating fumes any time during our visit. Of the several barges at the site only one particular barge appeared to have odors but this could not be detected until one got close to the barge dry dock area.

We talked with General Manager Micky Tinner to assess Mr. Castle's complaints. He said he was aware of Mr. Casale's concerns and had taken measures to prevent discomforts that might be irritate area residents.

Mr. Tinner stated that policies had been implemented to prevent any sand from the sandblasting operations to drift onto properties toward the Bridge Harbor area when Mr. Casales's concerns were first raised. According to Mr. Tinner, Hercules Offshore Drilling's policy is to discontinue all operations when winds blow out of the Northeast toward Bridge Harbor. Mr. Tinner showed us the techniques used in measuring the distance and direction in which the sand moves during blasting operations. Mr. Tinner mentioned that it was very costly to shut his operations down when the winds blew out of the Northeast.

Mr. Tinner mentioned that his company was trying to eliminate concerns regarding sand coming from his business by erecting a 24 foot tall and 400 foot long tennis court-type fence made of plastic material around the sandblasting operation in such a way that it would create a wind tunnel and help direct air flow away from the direction of the Bridge Harbor subdivision. The fence materials are on order and the fence should be erected soon.

We asked Mr. Tinner about Mr. Casale's concerns of being exposed to dangerous chemicals at his residence, particularly the incident Mr. Casale refered to in his letter of October 10, 1989, where he states that "residents were heavily exposed to benezene gas." Mr. Tinner said that the barge Mr. Casale was concerned about had unloaded the chemical Benezene in Houston and its tanks flushed before arriving at his facility. According to Mr. Tinner the only reason Mr. Casale knew that the barge had contained Benzene products was because he had read warning signs on the side of the barge with his binoculars as he often does.

Mr. Tinner stated that before work was done on any barges brought to his facility they must be inspected and certified before his men can go inside to do any hot work or cleaning. Certified equipment (air detectors) must

be used to perform such inspections and are necessary to get the certification that is required of Hercules Offshore Drilling. We were shown original documents of certificates where permission was received to begin work on barges. We were told that all the certificates and records were kept on file at all times to show what barges are brought on the premises.

Mr. Tanner mentioned that precautions are taken to insure the safety of his employees as well as the community. He said that they sometimes have up to forty five men working in and around the barges on a daily basis.

Mr. Tinner said that he has talked to the Texas Air Control Board in the past and that they have been to his business to monitor the quality of air in the surrounding area. (I personally have not seen the Texas Air Control Board's findings at this time).

We asked Mr. Tinner about Mr. Casale's noise complaint and he stated that a majority of the noise Mr. Casale complains of comes during the very late or early hours of the morning. Mr. Tinner said his men work occasional overtime until 7:00 or 8:00 p.m. at night but their usual work hours are from 7:30 a.m. to 3:30 p.m. They do work overtime on some weekends if they have to get a barge contract completed. We discussed with Mr. Tanner the City's noise ordnances restricting loud noises from 11:00 p.m until 7:00 a.m Sunday through Saturday and from 11:00 p.m Saturday through Sunday afternoon until 1:00 p.m and told him that we expected the ordinances would continue to be observed.

DATE: 10-13-89

TO: Meryl Walters and Earl Health

FROM: Robby L. Blair

RE: Investigation of Mr. Bob Casale's Complaints regarding the exposure to dangerous chemicals, exposure to sand-blasting materials, and loud abusive noises at Bridge Harbor per his letter addressed to the City of Freeport dated October 10, 1989.

An investigation of Mr. Casale's complaint was made October 13, 1989 at 9:00 a.m. The Brazoria County Health Department was asked to assist Larry Fansher and myself with this inspection. Upon arriving at Mr. Casale's residence we looked for signs of dead vegetation, leaves, trees, weeds, or grass both on the premises and along the canal. During this time no odors, eye irritating fumes or dead foliage at Mr. Casale's home was smelled or seen.

We spoke with Mr. Casale concerning his complaints. He stated that Hercules Offshore Drilling Company was responsable for exposing him and his family to hazardous odors as well as sandblasting materials and abusive loud noises. Mr. Casale showed us what appeared to be dust particles on his furniture located in his screened-in patio area and said it was coming from Hercules Offshore Drilling.

The Brazoria County Health Inspector asked Mr. Casale if her or any of the residents in the area had sought medical attention for chemical exposure or chemical related illnesses. Mr. Casale said that some residents had been to the doctor but was not sure if any doctors determined chemical smells to be the cause of any illnesses. The Bazoria County Health Inspector informed Mr. Casale that it would be helpful if any resident who felt that they were exposed to a dangerous chemicals should have documentation from the medical field or doctors' reports to help support any evidence of chemical exposure. Mr. Casale said people in the subdivision could not afford to keep going to doctors for treatment, and this financial burden was being placed on the residents.

Mr. Casale complained of loud noises coming from Hercules during the late night hours. He stated that they were coming from the barges as they opened and closed the hatches.

We told Mr. Casale that we would talk with other residents in the area as well as the management of Hercules Offshore Drilling Company. We left the house and went to our car located on Snapper Lane where we were able to observe at a distance sandblasting operations taking place at Hercules Offshore Drilling Company. What appeared to be sand particles could be seen around the barge that was being worked on but was seen only around the barge and we could not feel or see any dust or sand nor smell any chemicals at that time.

DATE: 10-13-89

TO: Meryl Walters and Earl Health

FROM: Robby L. Blair

RE: Investigation of Mr. Bob Casale's Complaints regarding the exposure to dangerous chemicals, exposure to sand-blasting materials, and loud abusive noises at Bridge Harbor per his letter addressed to the City of Freeport dated October 10, 1989.

An investigation of Mr. Casale's complaint was made October 13, 1989 at 9:00 a.m. The Brazoria County Health Department was asked to assist Larry Fansher and myself with this inspection. Upon arriving at Mr. Casale's residence we looked for signs of dead vegetation, leaves, trees, weeds, or grass both on the premises and along the canal. During this time no odors, eye irritating fumes or dead foliage at Mr. Casale's home was smelled or seen.

We spoke with Mr. Casale concerning his complaints. He stated that Hercules Offshore Drilling Company was responsable for exposing him and his family to hazardous odors as well as sandblasting materials and abusive loud noises. Mr. Casale showed us what appeared to be dust particles on his furniture located in his screened-in patio area and said it was coming from Hercules Offshore Drilling.

The Brazoria County Health Inspector asked Mr. Casale if her or any of the residents in the area had sought medical attention for chemical exposure or chemical related illnesses. Mr. Casale said that some residents had been to the doctor but was not sure if any doctors determined chemical smells to be the cause of any illnesses. The Bazoria County Health Inspector informed Mr. Casale that it would be helpful if any resident who felt that they were exposed to a dangerous chemicals should have documentation from the medical field or doctors' reports to help support any evidence of chemical exposure. Mr. Casale said people in the subdivision could not afford to keep going to doctors for treatment, and this financial burden was being placed on the residents.

Mr. Casale complained of loud noises coming from Hercules during the late night hours. He stated that they were coming from the barges as they opened and closed the hatches.

We told Mr. Casale that we would talk with other residents in the area as well as the management of Hercules Offshore Drilling Company. We left the house and went to our car located on Snapper Cane where we were able to observe at a distance sandblasting operations taking place at Hercules Offshore Drilling Company. What appeared to be sand particles could be seen around the barge that was being worked on but was seen only around the barge and we could not feel or see any dust or sand nor smell any chemicals at that time.



128 EAST 4TH STREET / FREEPORT, TEXAS 77541 / (409) 233-3526

October 16, 1989

In summary to this preliminary report I have spoken to Ms. Mary Knotts of the Compliance Section of the Texas Air Control Board on the 16th of October 1989, to request that I accompany her on investagation of Mr. Casale's complaint. She is scheduled to arrive in Freeport Tuesday October 17, 1989.

As of this date there are two complaint reports at Bridge Harbor; one dated October 10, 1989 and one dated October 13, 1989. A complete report will follow after above inspection with Air Control Inspector.

Sincerely

Robby L. Blair Building Official City of Freeport

RLB:sd

#### UVIOLATION FOLLOWUP D.P. VIOLATION Blue - Region/Local Piogram Canary - Data Entry/Region Pink - Investigator INVESTIGATION/VIOLATION FORM (BOLDFACED ITEMS ARE REQUIRED) ⊠ Add Change Pink - Investigator/Data Entry Delete Account Number & LO | 18 V Account Name: HEACULES OFFSHORE Date of Investigation (as MMDDYY) | O 26 89 Off Hours (Y or N) Y Investigator Staffcode DOM ( Permit(s): 1 Primary Investigator Juriscode O 10 Other Juriscode 1 Other Juriscode 2 Site Name/Location: Person Contacted/Phone: Person Contacted/Phone: Investigation Number 33 7202 A Related Previous Investigation Number Federal Program (Y or N): NSPS NESHAP Situation Number (COMPLIANCE DIV. ONLY) \*Investigation Type Cos / In-House Investigation (Y or N) (FPN) 2 SULVEILLANCE \_\_\_\_ DETECTED DUBLING AFTER HUMES \* \* \* FOR RECORDING REVIEWS OF COMPANY-SUBMITTED REPORTS ONLY \* \* \* Date Test Conducted (as MMDDYY) \_ \_ \_ Date Report Received (as MMDDYY) \_ \_ \_ Analysis Review Results (C,N,U) \_ Permit(s): \_\_\_\_\_ Retest Required? Investigation Number Related Previous Investigation Number Federal Program (Y or N): NSPS NESHAP Situation Number (COMPLIANCE DIV. ONLY) \*Investigation Type \_\_\_\_ In-House Investigation (Y or N) \_ \*\*EPN \_\_\_\_\_ Investigation Number Local Ordinance (Y or N) Violation Number (CHANGES/DELETES ONLY) Situation Number (COMPLIANCE DIV. ONLY) Local Ordinance (Y or N) (COMPLIANCE DIV. ONLY) Cause/Description -\_\_\_Contamcode Rule Violated Fill in the Following Applicable Items: Permit Number Board Order Number Court Order Number Facility Name (optional) \*FIN Involved Violation Type (C-Clerical, N-Non-Clerical, I-Imminent Danger) Date NOV Sent (as MMDDYY) Date NOV Received (as MMDDYY) \_ \_ \_ \_ (DEFAULTS TO 5 DAYS AFTER DATE NOV SENT) Investigation Number Local Ordinance (Y or N) Investigation Number (CHANGES/DELETES ONLY) Situation Number (COMPLIANCE DIV. ONLY) (COMPLIANCE DIV. ONLY) Contamcode Cause/Description Rule Violated Fill in the Following Applicable Items: Permit Number Permit Provision Board Order Number Court Order Number Involved Facility Name (optional) \*FIN Involved Violation Type (C=Clerical, N=Non-Clerical, I=Imminent Danger) Date NOV Sent (as MMDDYY) Date NOV Received (as MMDDYY) (DEFAULTS TO 5 DAYS AFTER DATE NOV SENT) \*SEE BACK FOR VALID CODES AND INVESTIGATION TYPE CODES MATRIX \*\*EPN REQUIRED FOR INVESTIGATION TYPES INDICATED ON BACK WITH AN \*

\*FIN REQUIRED FOR VOC VIOLACTIONS AS INDICATED WITH A + IN THE USER'S MANUAL RULE TABLE

Investigator Signature: Wayse WM

Screen ID: IV1, IVI1, VLl. Page of Pages

Approved By:

# Wilth Date: 10/20/89

Date: 11/3/89

ACB 93A (12/1/87)

T & E 000444

	Date 10/30/89
	Date 10/30/89 10:25 am 5:
Person making call Mary Knotts	Tel. 666-4964
Organization Region 7	Location Bellaire.
erson receiving call . Steve Davis	Tel. 824-7362.
organization <u>Public Information</u>	n Location Austin
ubject Hadia Contact: Brazospor Offshore, Francost.	t Facts Regarding Hercules
ummary: I called Stove to	
a telephone conversation 7	
Chambers of the "Brazos	
in Clute. Mr. Chambers	
more about the complaints	_
Hereules Offshore; à barge Mes	
operation. I informed Mr.	Chambre that use
had received complaints a	Ilian Sun Mulsayay
due to dust from sand blast	
due to the venting of	
the barges I told Mr. (	
acrielation votice had been	issued Soc dust from
sand blasting but no muis	
been documented related of	n 1/0 Any & missione Som
the barges.	
-	ሞዴሞ በበበለ1 ለ

Time	: 10:25 am fil
Person making call Mary Knotts  Organization Region 7	Tel. 666-4964  Location Belleine.
Person receiving call. Steve Davis TACB Public Information	Tel. 8\$4-7362 Location Austin
Subject Hedia Contact: Brazosport Fact: Offshore, Freeport.	BL=0118-VA s Regarding Hercules
a telephone conversation I had Chambers of the Brazosport Fin Clute. Mr. Chambers wants more about the complaints to a Hereules Offshore; a barge cleaning operation. I informed Mr. Chambrad received complaints allegated to dust from sandblasting a due to dust from sandblasting a due to the venting of varior the barges. I told Mr. Chambrad acviolation votice had been issue sandblasting. But no nuisance been documented related to varior the barges.	acts News paper ed to know ar requery about and refurbish bers that we ind nuisance and nuisance ind nuisance is vapors from ers also that
	T&E 000061

DATE 10/30/89

4	DACE 10   8
	Time 10:25 am File
Person making call Mary Knotts	Tel. 666-4964
Organization Region 7	Location Bellacine.
Person receiving call. Steve Davi	Tel. 8\$4-7362
Organization Public Informati	
Subject Hedia Contact: Brazospor Offshore, Freeport.	t Facts Regarding Hercules
Summary: I called Stove to	_
a telephone conversation	t had with Ken
Chambers of the "Brazos	<i>11</i>
in Clute Mr. Chambers	
more about the complaints	<b>.</b>
Herenles Offshore; a barge che	aning and refurbish
operation. I informed Mr	\ \
had received complaints	
due to dust from sand blast	
due to the venting of	
the barges I told Mr.	
a violation Notice had been	4 4
sand blasting. But no nuis	
been documented related of	to vapor emissions for
the bargues.	
. *	

# Texas Air Control Board

Austin

TEXAS

11-1-85 C

### INTEROFFICE

ACCOUNT NAME: 14	ecules Off sho	C ACCOUNT NO. 13 LO1180
		vepair
Investigation Date:	8/2/89	Violation(s): 101.4 /4.00
Date of NOV Letter:	9/19/89	Investigator: mAIC / pm
Date NOV Received:	9/20/89	(Defaults to 5 days after NOV)
Response Due:	10/2/89	Response Received: 10/6/89
FEC Date:	· · · · · · · · · · · · · · · · · · ·	•
RECOMMENDED ACTION:	:	
CONTESTED (	R ONLY R w/ADMIN. PENALTY CASE HEARING DRCEMENT ACTION	PERMIT REVOCATION
RESOLUTION DATE:	ACTUAL COMPLIANCE	DATE
	PROJECTED COMPLIA	NCE DATE
INFORMAL RESOLUTION	N METHOD:	(DOCUMENT COPY ATTACHED)
INVESTIGAT LETTER FROM MEMORANDUM RESOLUTIO	M SOURCE INDICATING	PERMIT ISSUED REGULATION CHANGED OUALIFIES FOR STANDARD EXEMPTION SAMPLING INDICATES RESOLUTION
FORMAL RESOLUTION:		
BOARD ORDER NO	•:	ORDER DATE:
COURT ORDER NO	·: <u> </u>	PENALTY AMOUNT:
COMMENTS:		



Strength through experience, equipment, know-how 11011 Richmond Ave., Suite 500 Office (713) 789-7983

Houston, Texas 77042

Fax. (713) 789-7983 Fax. (713) 789-4063

S Air Control Board

October 2, 1989

Air Quality Control
Region 7
5555 West Loop
Suite 300
Bellaire, Texas 77401

Re: Notice of Violation General Rule 101-4 Account No. BL-0118-V

Dear Ms. Mary Knotts:

This letter is in response to the violation that we received for our Sandblasting project.

To eliminate any further violations, Hercules Offshore will not do any sandblasting when the wind is out of an Easterly direction.

Thank you for your time and cooperation.

Sincerely,

Mickey W. Tiner General Manager

MWT/se

## Texas Air Control Board

AusTIN

TEXAS

11-1-89 CK

)FFI	RO	ER	INT	۱

	Herbert W. Williams, Jr. Regional Director, Houston	Sabino Gomez, M.P.H.  Director, Compliance Div.
_	Subject: NOV Status/Response Eva	luation & Resolution Notice
	ACCOUNT NAME: Hecules Off	shore G ACCOUNT NO. 13 LO1180
	Facility Involved: 60	crate repair
	Investigation Date: 8/1/87	Violation(s): 101.4 /4.01(a)
	Date of NOV Letter: 9/19/89	Investigator: mAK/pm
	Date NOV Received: 9/20/89	(Defaults to 5 days after NOV)
	Response Due: 10/2/89	Response Received: 10/6/89
	FEC Date:	<u> </u>
	RECOMMENDED ACTION:	
	BOARD ORDER ONLY BOARD ORDER W/ADMIN. PENA CONTESTED CASE HEARING FORMAL ENFORCEMENT ACTION	PERMIT REVOCATION
	RESOLUTION DATE: ACTUAL COMPL	IANCE DATE
	PROJECTED CO	MPLIANCE DATE
	INFORMAL RESOLUTION METHOD:	(DOCUMENT COPY ATTACHED)
	DELETED, NOV NOT VALID INVESTIGATION LETTER FROM SOURCE MEMORANDUM INDICATING RESOLUTION RECORD OF TELEPHONE CALL	PERMIT ISSUED REGULATION CHANGED OUALIFIES FOR STANDARD EXEMPTION SAMPLING INDICATES RESOLUTION
	FORMAL RESOLUTION:	
	BOARD ORDER NO.:	ORDER DATE:
	COURT ORDER NO.:	PENALTY AMOUNT:
•	COMMENTS:	· .
		1810
		SIGNED JULIANS



Strength through experience, equipment, know-how

11011 Richmond Ave., Suite 500 Houston, Texas 77042 Office (713) 789-7983 Fax (713) 789-4063

S Air Control Board

October 2, 1989

Air Quality Control
Region 7
5555 West Loop
Suite 300
Bellaire, Texas 77401

Re: Notice of Violation General Rule 101-4 Account No. BL-0118-V

Dear Ms. Mary Knotts:

This letter is in response to the violation that we received for our Sandblasting project.

To eliminate any further violations, Hercules Offshore will not do any sandblasting when the wind is out of an Easterly direction.

Thank you for your time and cooperation.

Sincerely,

Mickey W. Tiner General Manager

MWT/se

### rexas Air Control Board

**AUSTIN** 

TEXAS

J. 9100	
CF	X-c
•	A-C
	11.

### INTEROFFICE

	Herbert W. Williams, Jr. Regional Director, Houston	Sabino Gomez, M.P.H.  Director, Compliance Div.
r	Subject: NOV Status/Response Evaluati	on & Resolution Notice
	ACCOUNT NAME: Hecules Off she	<del> </del>
	Facility Involved: 6avqe	
	Investigation Date: 8/1/87	Violation(s): 101.4 /4.01ca
	Date of NOV Letter: 9/19/89	Investigator: mpc/pm
	Date NOV Received: 9/20/89	(Defaults to 5 days after NOV)
	Response Due: 10/2/89	Response Received: 10/6/89
	FEC Date:	•
•	RECOMMENDED ACTION:	
	BOARD ORDER ONLY BOARD ORDER W/ADMIN. PENALTY CONTESTED CASE HEARING FORMAL ENFORCEMENT ACTION	INFORMAL ENFORCEMENT ACTION LEGAL ACTION PERMIT REVOCATION UNDECIDED
	RESOLUTION DATE: ACTUAL COMPLIANCE	DATE
	PROJECTED COMPLIA	ANCE DATE
	INFORMAL RESOLUTION METHOD:	(DOCUMENT COPY ATTACHED)
	DELETED, NOV NOT VALID INVESTIGATION	PERMIT ISSUED REGULATION CHANGED
	LETTER FROM SOURCE MEMORANDUM INDICATING RESOLUTION RECORD OF TELEPHONE CALL	QUALIFIES FOR STANDARD EXEMPTION SAMPLING INDICATES RESOLUTION
	LETTER FROM SOURCE MEMORANDUM INDICATING RESOLUTION	EXEMPTION
	LETTER FROM SOURCE MEMORANDUM INDICATING RESOLUTION RECORD OF TELEPHONE CALL	EXEMPTION SAMPLING INDICATES RESOLUTION
	LETTER FROM SOURCE MEMORANDUM INDICATING RESOLUTION RECORD OF TELEPHONE CALL FORMAL RESOLUTION:	EXEMPTION SAMPLING INDICATES RESOLUTION ORDER DATE:

T&E 000458

ţ



Strength through experience, equipment, know-how

11011 Richmond Ave., Suite 500 Houston, Texas 77042

Office (713) 789-7983 Fax (713) 789-4063

Star Air Control Board

Charles The

October 2, 1989

Air Quality Control Region 7 5555 West Loop Suite 300 Bellaire, Texas 77401 >

Re: Notice of Violation General Rule 101-4 Account No. BL-0118-V

Dear Ms. Mary Knotts:

This letter is in response to the violation that we received for our Sandblasting project.

To eliminate any further violations, Hercules Offshore will not do any sandblasting when the wind is out of an Easterly direction.

Thank you for your time and cooperation.

a. Vinen

Sincerely,

Mickey W. Tiner General Manager

MWT/se